
Office	State of New Mexico	Form C-103
' <u>District I</u> Energy, N	Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-025-20726
1301 W. Grand Ave., Artesia, NM 88210 OIL CO	NSERVATOR DIVISION	5. Indicate Type of Lease
District III 122	20 South St. Francis larg 018	STATE FEE
District IV	Santa Fe, NM\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	ORTS ON WELLS R TO DEEPEN OR PLUG BACK TO A	
SUNDRY NOTICES AND REPO	ORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL O	R TO DEEPEN OR PLUG BACK TO A	LSA
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM PROPOSALS.)	MIT" (FORM C-101) FOR SUCH	8. Well Number
1. Type of Well: Oil Well Gas Well 🖂 G	Other	1
2. Name of Operator		9. OGRID Number
Marathon Oil Permian, LLC		372098
3. Address of Operator		10. Pool name or Wildcat
5555 San Felipe Houston, TX 77056		Double A, ABO, South
4. Well Location	N. 11 1 1000 C . C . 1	
Unit Letter_G:1980feet from the		
Section 30 Township 17S	<u> </u>	MPM County LEA
11. Elevation	(Show whether DR, RKB, RT, GR, etc.)	and all and any arrespond
Pit or Below-grade Tank Application or Closure	3881	COURT OF A
	ce from nearest fresh water well Dist	ance from nearest surface water
·· —		onstruction Material
12. Check Appropriate Bo	ox to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO	O SUB	SEQUENT REPORT OF:
	BANDON REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE PLA		_
PULL OR ALTER CASING MULTIPLE CO	<u> </u>	
PULL OR ALTER CASING MULTIPLE CO	DMPL CASING/CEMENT	
PULL OR ALTER CASING MULTIPLE CO	OMPL CASING/CEMENT OTHER:	T JOB
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations.	OMPL CASING/CEMENT OTHER: (Clearly state all pertinent details, and	T JOB
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE	OMPL CASING/CEMENT OTHER: (Clearly state all pertinent details, and	T JOB
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations.	OMPL CASING/CEMENT OTHER: (Clearly state all pertinent details, and	T JOB
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.	OMPL CASING/CEMENT OTHER: (Clearly state all pertinent details, and	T JOB
PULL OR ALTER CASING ☐ MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. ✓	OMPL CASING/CEMENT OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Att	T JOB
PULL OR ALTER CASING ☐ MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. ✓	OMPL CASING/CEMENT OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Att	T JOB
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' - 5131' tag. 3. 40sx 5130' - 5010'. WOC TAGE. 440 25sx 4547' - 4447'	OMPL CASING/CEMENT OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Att	T JOB
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' - 5131' tag. 2. 40sx 5130' - 5010'. WOC ITA G. 440 26sx 4547' - 4447' 540 35sx 3293' - 3193'.	OMPL CASING/CEMENT OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Att	T JOB
PULL OR ALTER CASING ☐ MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. ✓ 2. 60sx 5315' − 5131' tag. ✓ 3. 40sx 5130' − 5010'. ✓ WOC ↓ TA ← 440 2/5sx 4547' − 4447' 540 3/5sx 3293' − 3193'. 6.40/5sx 1950' − 1850'.	OMPL CASING/CEMENT OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Att	T JOB
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' - 5131' tag. 2. 40sx 5130' - 5010'. WOC ITA G. 440 26sx 4547' - 4447' 540 35sx 3293' - 3193'.	OMPL CASING/CEMENT OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Att	I JOB
PULL OR ALTER CASING ☐ MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' − 5131' tag. < 3. 40sx 5130' − 5010'. ✓ WOC 440 25sx 4547' − 4447' 540 25sx 3293' − 3193'. 6.405sx 1950' − 1850'. 7. 165sx 496' − Surf. Install DHM.	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: At	I JOB
PULL OR ALTER CASING ☐ MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. ✓ 2. 60sx 5315' − 5131' tag. ✓ 3. 40sx 5130' − 5010'. ✓ WOC ↓ TA ← 440 2/5sx 4547' − 4447' 540 3/5sx 3293' − 3193'. 6.40/5sx 1950' − 1850'.	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion See Attached
PULL OR ALTER CASING ☐ MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' − 5131' tag. < 3. 40sx 5130' − 5010'. ✓ WOC 440 25sx 4547' − 4447' 540 25sx 3293' − 3193'. 6.405sx 1950' − 1850'. 7. 165sx 496' − Surf. Install DHM.	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion See Attached
PULL OR ALTER CASING ☐ MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. ✓ 2. 60sx 5315' − 5131' tag. ✓ 3. 40sx 5130' − 5010'. ✓ WOC → TA ← . 440 → 5sx 4547' − 4447' 540 → 5sx 3293' − 3193'. 6.40 → 5sx 1950' − 1850'. 7. 165sx 496' − Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' − 9324' cemented	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: At	I JOB
PULL OR ALTER CASING ☐ MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. ✓ 2. 60sx 5315' − 5131' tag. 3. 40sx 5130' − 5010'. ✓ WOC → TA ← . 440 → 5sx 4547' − 4447' 540 → 5sx 3293' − 3193'. 6.40 → 5sx 1950' − 1850'. 7. 165sx 496' − Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' − 9324' cemented P&A mud between all plugs.	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion See Attached
PULL OR ALTER CASING ☐ MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. ✓ 2. 60sx 5315' − 5131' tag. 3. 40sx 5130' − 5010'. ✓ WOC → TA ← . 440 → 5sx 4547' − 4447' 540 → 5sx 3293' − 3193'. 6.40 → 5sx 1950' − 1850'. 7. 165sx 496' − Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' − 9324' cemented P&A mud between all plugs. Closed loop.	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion See Attached
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' - 5131' tag. < 3. 40sx 5130' - 5010'. WOC TAGE. 440 25sx 4547' - 4447' 540 25sx 4547' - 4447' 540 25sx 1950' - 1850'. 7. 165sx 496' - Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' - 9324' cemented P&A mud between all plugs. Closed loop. All fluids to licensed facility.	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Att	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion See Attached Conditions of Approval
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' – 5131' tag. < 3. 40sx 5130' – 5010'. WOC * TA G. 440 2/5sx 4547' – 4447' 540 3/5sx 3293' – 3193'. 6.40 3/5sx 1950' – 1850'. 7. 165sx 496' – Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' – 9324' cemented P&A mud between all plugs. Closed loop. All fluids to licensed facility. I hereby certify that the information above is true and	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Attended to the best of my knowledged complete to the best of my knowledged to the best of my	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion See Attached Conditions of Approval e and belief. I further certify that any pit or below-
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' – 5131' tag. < 3. 40sx 5130' – 5010'. WOC * TAC. * 440 *25sx 4547' – 4447' 540 *25sx 4547' – 4447' 540 *25sx 1950' – 1850'. 7. 165sx 496' – Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' – 9324' cemented P&A mud between all plugs. Closed loop. All fluids to licensed facility. I hereby certify that the information above is true and grade tank has been/will be constructed or closed according to the start of the start	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: At CSG. Complete to the best of my knowledge NMOCD guidelines , a general permit	See Attached Conditions of Approval e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' – 5131' tag. < 3. 40sx 5130' – 5010'. WOC * TA G. 440 2/5sx 4547' – 4447' 540 3/5sx 3293' – 3193'. 6.40 3/5sx 1950' – 1850'. 7. 165sx 496' – Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' – 9324' cemented P&A mud between all plugs. Closed loop. All fluids to licensed facility. I hereby certify that the information above is true and	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Attended to the best of my knowledged complete to the best of my knowledged to the best of my	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion See Attached Conditions of Approval e and belief. I further certify that any pit or below-
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' – 5131' tag. < 3. 40sx 5130' – 5010'. WOC TAGE. 440 25sx 4547' – 4447' 540 35sx 3293' – 3193'. 6.40 5sx 1950' – 1850'. 7. 165sx 496' – Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' – 9324' cemented P&A mud between all plugs. Closed loop. All fluids to licensed facility. I hereby certify that the information above is true and grade tank has been/will be constructed or closed according to SIGNATURE	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Att CSCSG. Complete to the best of my knowledge on NMOCD guidelines , a general permit TITLE Agent	See Attached Conditions of Approval e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan □. DATE 1/06/2018
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' – 5131' tag. 3. 40sx 5130' – 5010'. WOC TAGE. 440 26sx 4547' – 4447' 540 36sx 3293' – 3193'. 6.40 5sx 1950' – 1850'. 7. 165sx 496' – Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' – 9324' cemented P&A mud between all plugs. Closed loop. All fluids to licensed facility. I hereby certify that the information above is true and grade tank has been/will be constructed or closed according to SIGNATURE Type or print name	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: At CSG. Complete to the best of my knowledge NMOCD guidelines , a general permit	See Attached Conditions of Approval e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' – 5131' tag. < 3. 40sx 5130' – 5010'. WOC TAGE. 440 25sx 4547' – 4447' 540 35sx 3293' – 3193'. 6.40 5sx 1950' – 1850'. 7. 165sx 496' – Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' – 9324' cemented P&A mud between all plugs. Closed loop. All fluids to licensed facility. I hereby certify that the information above is true and grade tank has been/will be constructed or closed according to SIGNATURE	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: At CSG. Complete to the best of my knowledge of NMOCD guidelines , a general permit TITLE Agent E-mail address:	See Attached Conditions of Approval e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan DATE 1/06/2018 Telephone No.
PULL OR ALTER CASING MULTIPLE CO OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 1. 5 ½ CIBP @ 8750' w/35sx cmt. < 2. 60sx 5315' – 5131' tag. 3. 40sx 5130' – 5010'. WOC TAGE. 440 26sx 4547' – 4447' 540 36sx 3293' – 3193'. 6.40 5sx 1950' – 1850'. 7. 165sx 496' – Surf. Install DHM. Note: 5 ½" 17lb. N-80 liner 5181' – 9324' cemented P&A mud between all plugs. Closed loop. All fluids to licensed facility. I hereby certify that the information above is true and grade tank has been/will be constructed or closed according to SIGNATURE Type or print name	OMPL OTHER: OTHER: (Clearly state all pertinent details, and E 1103. For Multiple Completions: Att CSCSG. Complete to the best of my knowledge on NMOCD guidelines , a general permit TITLE Agent	See Attached Conditions of Approval e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan □. DATE 1/06/2018



Wellbore Schematic Well Name: LSA 1

State/Province Prospect Area Field Name Well Subtype Lat/Long Datum Latitude (*) Longitude (*)
NEW MEXICO OIL WELL NAD27 32,807454 -103,391396
Well Configuration Type Well Objective Well Status PRODUCING 3,881.00 11,00



After

MAVERICK WELL PLUGGERS

COMPANY: Marathon O:1 Permian

WELL NAME: LSA


WELL#:

COUNTY: Lea

LEASE ID:

API-30-025-20726

SURFACE CASING						
ao	WT/FT	GRADE	SET AT	TOC		
133/8"			446			
INTERMEDIATE CASING						
OD	WI/FT	GRADE	SETAT	TOC /		
9 5/8			5254	5265		
						
	PRO	DUCTION CA	SING			
OD	PRO WT/FT	DUCTION CA GRADE	SING SET AT	10C		
OD 5 1/2 "	WT/FT			10C		
OD 5 1/2 "				100		
OD S 1/2 11	WT/FT	GRADE		TOC		



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.