	State of New Michieu			Form C-103		
District I – (575) 393-6161 District I – (575) 393-6161 District I – (575) 393-6161			Revised July 18, 2013 WELL API NO.			
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			20 025 26004		-	
811 S. First St., Artesia, NM 88210 NOV 2 926 GONSERVATION DIVISION District III – (505) 334-6178 1220 South St. Francis Dr.			5. Indicate Type of Lease		1	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 RECEIVED Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM			STATE FEE X - 6. State Oil & Gas Lease No.		-	
1220 S. St. Francis Dr., Santa Fe, NM 87505			o. State Off & G	as Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name		1	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Eunice No#-901 BW-902- 8. Well Number #1			
1. Type of Well: Oil Well Gas Well Y Other Brine			77 2		_	
2. Name of Operator Basic Energy Services			9. OGRID Number 246368			
3. Address of Operator PO Box 1375, Artesia, NM 88211			10. Pool name or Wildcat Salado			
4. Well Location						
Unit Letter 0 : 630 feet from the South line and 2427 feet from the East line						
Section 34 Township 21S Range 37E NMPM County Lea						
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:					
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK				ALTERING CASING		
TEMPORARILY ABANDON			_	P AND A		
PULL OR ALTER CASING			JOB 🗆			
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM						
OTHER: OTHER:						
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
Place rig over hole and set B.O.P Remove all 2 7/8 production tubing and run in with 4 1/2 tubing with notched mule shoe. Drill down to bottom of cavern. Run sonar as required by OCD. Run out of the hole with 4 1/2" and back with new 2 7/8" tubing.						
	,-					
				BW-002	-	
Spud Date: 11-30-18 Rig	Release Da	ite:				
Λ						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE DATE 11-28-18						
Type or print name 7 ARY RITCHIEFT E-mail address: GARY, PRITCHETT PHONE: 432-213-6641 For State Use Only A BASIC ELERGY SIZIVICES. COM						
For State Use Only M SASIC ENERGY SIENVICES, COM						
APPROVED BY: YOUNG OF APPROVED GO APPROVED BY: DATE 11/29/2018						
Conditions of Approval (if any):		•		<i>v i</i>		