

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised August 1, 2011

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-00954 ✓
1. Type of Well: Oil Well   Gas Well   Other <u>INJECTION</u> ✓		5. Indicate Type of Lease STATE   X   FEE   ✓
2. Name of Operator State of New Mexico formerly Canyon E&P Company <u>DEC 03 2018</u>		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive   Hobbs, NM 88240 <u>RECEIVED</u>		7. Lease Name or Unit Agreement Name Artesia Metex Unit ✓
4. Well Location Unit Letter <u>H</u> : <u>2310</u> feet from the <u>North</u> line and <u>990</u> feet from the <u>East</u> line Section <u>25</u> Township <u>18S</u> Range <u>27E</u> NMPM <u>Eddy</u> County <u>✓</u>		8. Well Number <u>040</u> ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 269864 ✓
10. Pool name or Wildcat Artesia QU-GB-SA ✓		10. Pool name or Wildcat Artesia QU-GB-SA ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**SEE ATTACHED**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_

**For State Use Only**

APPROVED BY: Mah White TITLE P.E.S. DATE 12/03/2018

Conditions of Approval (if any):

*MW*

Canyon E&P Company  
Artesia Metex Unit #40  
30-015-00954  
2310 FNL & 990 FEL  
UL-H, Sec 25, T18S, R27E

8 5/8" csg set at 500' w/50 sx cmt


4 1/2" csg set at 2099' w/250 sx cmt Top of cement by TS @ 1740'

Perforations: 1675'-79' Squeezed with 150 sx Class "C" 6/22/1977

Perforations: 1882'-2012'

1. MIRU and POOH with plugging equipment.
2. Make gauge ring run and set 4 1/2" CIBP at 1782'. Circulate MLF and test casing to 500#.
3. Spot 35 sx cmt on top of CIBP.
4. Perforate 4 1/2" casing at 550'. Pump sufficient cement to circulate to surface inside and outside of 4 1/2" casing.
5. Cut off wellhead 3' below ground level.
6. Verify cement to surface on all strings of casing.
7. Install upright marker and cut off anchors.

State of New Mexico for Canyon  
E&P Company  
Artesia Metex Unit #40  
API 30-015-00954  
WBD Before PA



State of New Mexico for Canyon  
E&P Company  
Artesia Metex Unit #40  
API 30-015-00954  
WBD After PA

