

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised August 1, 2011

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-01191 ✓
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator State of New Mexico formerly Canyon E&P Company		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240		7. Lease Name or Unit Agreement Name Artesia Metex Unit ✓
4. Well Location Unit Letter <u>O</u> : <u>1060</u> feet from the <u>South</u> line and <u>1560</u> feet from the <u>East</u> line Section <u>26</u> Township <u>18S</u> Range <u>27E</u> NMPM <u>Eddy</u> County ✓		8. Well Number 050 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 269864 ✓
RECEIVED HOBBSS OCD		10. Pool name or Wildcat Artesia QU-GB-SA ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**SEE ATTACHED**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_

**For State Use Only**

APPROVED BY: Mark W. Pitzer TITLE P.E.S. DATE 12/05/2018

Conditions of Approval (if any):

Canyon E&P Company  
Artesia Metex Unit #50  
30-015-01191  
1060' FSL & 1560 FEL  
UL-O, Sec 26, T18S, R27E

8 5/8" csg set at 550' Mudded with 6 sx

5 1/2" 14# csg set at 1940' with 35 sx cement. Cut and pulled from 1553'. No date when pulled.

4 1/2" csg set at 1628' and cemented with 50 sx. Re-entered in 1970


Original TD: 2134'

PBTD: 1958'

Open Hole: 1940'-1958'

1. MIRU and POOH with production equipment.
2. Make gauge ring run and set 4 1/2" CIBP at 1528'. Circulate MLF and test casing to 500#.
3. Spot 35 sx cement on top of CIBP.
4. Perforate 4 1/2" casing at 542'. Pump sufficient cement to circulate cement to surface inside and outside of 4 1/2" casing.
5. Cut off wellhead 3' below ground level.
6. Verify cement is to surface on all strings of casing.
7. Install upright marker and cut off anchors.

State of New Mexico for Canyon E&P  
Company  
Artesia Metex Unit #50  
API 30-015-01191  
WBD After PA



State of New Mexico for Canyon E&P  
Company  
Artesia Metex Unit #50  
API 30-015-01191  
WBD After PA

