Submit 1 Com To Anonomiato District				
Submit 1 Copy To Appropriate District Office	State of New Mexico	res Form C-103 Revised July 18, 2013		
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resource	WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DV SIC	3 002545372		
District III - (505) 334-6178	1220 South Sol Pancis Dr.	5. Indicate Type of Lease STATE STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505 2019	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505	JAN I FLOID			
SUNDRY NOTICES AND REPORTS ON WELLS FIVED		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DRIEL OF BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		A CARAVAN 285 STATE COM		
PROPOSALS.)		8. Well Number 703H		
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator		9. OGRID Number		
EOG RESOURCES		7377		
3. Address of Operator		10. Pool name or Wildcat		
P O BOX 2267, MIDLAND TX 79702				
4. Well Location Unit Letter <u>C</u> : 483 feet from the <u>NORTH</u> line and <u>1411</u> feet from the <u>line</u>				
Section 28	Township 24S Range 33			
Ball have a second start of a second st	11. Elevation (Show whether DR, RKB, RT, G			
	3525 GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
12. Check	Appropriate Box to indicate Nature of No	otice, Report of Other Data		
	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
TEMPORARILY ABANDON		CE DRILLING OPNS.⊠ P AND A □ EMENT JOB ⊠		
		DRILL CSG		
OTHER: 13. Describe proposed or com	Deted operations. (Clearly state all pertinent deta	hils, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
12/20/18 SPUD 12-1/4" HOLE				
Surface Casing @ 1,298'				
Run 9-5/8" 40# J-55 LTC Lead Cement w/ 580 sx Class C(1.76 yld, 13.5 ppg), Tail w/ 90 sx Class C (1.36 yld, 14.8 ppg) Test casing to 1,500 psi for 30 min - Good Circ 303 sx ce <u>ment to s</u> urface				
01/01/19 8-3/4" hole				
01/01/19 Intermediate Casing @ 11,826' Run 7-5/8'', 29.7#, HCP-110 BTC SCC (0' - 978')				
Run 7-5/8", 29.7#, HCP-110 MO-FXL (978' - 11,826') Lead Cement w/ 435 sx Class C (3.62 yld, 9.0 ppg), follow w/175 sx Class C (2.55 yld, 11.0 ppg), Tail w/ 180 sx Class C(1.11 yld, 14.2 ppg)				
Test casing to 1500 psi for 30 min - OK. Did not circ cement to surface, Ran CBL, TOC@1500 MD, conducted PIT to 500psi for 30 min,				
Resumed Drilling				
Spud Date: 12/20/18	Rig Release Date:			
L				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
Thereby certify that the information above is true and complete to the best of my knowledge and benef.				
SIGNATURE MM FILLE Sr. Regulatory Administrator DATE 01/10/19				
SIGNATURE M DICH TITLE Sr. Regulatory Administrator DATE 01/10/19				
Type or print name Emily Folis E-mail address: "emily_follis@ugresources.comONE: 432-848-9163				
For State Use Only				
APPROVED BY:				
Conditions of Approval (Fany):				

Santos Gonzales

From:	Reed Cupps		
Sent:	Monday, January 7, 2019 5:51 PM		
Το:	Santos Gonzales; Ben Hocher; Sam Biffle; HP 621 Rig		
Cc:	Steve Munsell; Domingo Lopez; Dewey McMillen; Aj Dach; Jason Townsend; Thomas		
	Thornton		
Subject:	Caravan 28 State Com #703H 7-5/8" cement job	HON	
Attachments:	CCF01072019.pdf	OBB [®]	
		HOBBS OCD	
Follow Up Flag:	Follow up	1420.	
Flag Status:	Flagged	REC - 2019	
		CENT	
		RECEIVED	

Men,

Just got off of the phone with Mark Whitaker, NMOCD engineer on call, regarding the forensics on the Caravan 28 State Com #703H that did not circulate cement to surface. Below is a summary of events on communications with the NMOCD

- 1. Circulated 8bbls spacer to surface.
- 2. Notified Mark Whitaker at NMOCD of results. Mark gave the directive to conduct a CBL and if cement is not lapped in previous surface casing shoe we would then be required to establish an injection rate + Braden head squeeze.
- 3. We conducted a CBL (iso-scanner) between our curve/lateral trips and noted TOC at 1,500'.
- 4. At 1300hrs, we attempted to establish an injection rate down the 7-5/8" x 9-5/8" casing annulus. With a 3rd party tester, we pressured up on the annulus to 500psi with the inability to establish injection
- 5. I then notified Mark Whiteless of the results and emphasized the inability to establish injection . Mark gave the community of the results and emphasized the inability to establish injection.
- 6. Action: Ben/Santos: Please populate NMOCD 103 with the above information and time log and submit with NMOCD as per Mark Whitaker. PIT pressure chart attached.
- 7. Action: Hector/Jeff: Please record the following verbiage in the comments section of the DDR. "Conducted CBL on Carevan 20 State Com #703H7 5/6" Casing string. TOC interpreted at 1,500' MD. Attempted to establish injection rate without success, conducted PIT to 500psi for 30 minutes (no pressure decline). Notified Mark Whitaker, NMOCD Engineer on Call, of results. Mark Whitaker gave verbal approval to continue operations on the Caravan 28 State Com #703H with no further remediation required."

Thanks,

Reed Cupps Drilling Engineer EOG Resources Midland Office: 432-848-9150 Cell: 432-212-2886 Email: **reed cupps@EOGResources.com**

