

Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
District 1 - (575) 393-6161	Energy, Minerals and Natural Resource	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-30486
District III - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		0. State Off & Gas Lease No.
87505		
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		South Hobbs (G/SA) Unit
PROPOSALS.)		8. Well Number: 223
	Gas Well Other:	
2. Name of Operator	10 B 1 2013	9. OGRID Number: 157984
Occidental Permian Ltd.	- Participation	
3. Address of Operator HCR 1 Box 90 Denver City, TX 79.	JAN WEEK	10. Pool name or Wildcat Hobbs (G/SA)
•		
4. Well Location	RE	
Unit LetterN:12	57feet from theSouth line and1	791feet from theWestline
Section 34	Township 18S Range	38E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3613' (GL)		
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] DOWNHOLE COMMINGLE [] 13. Describe proposed or compl of starting any proposed wo proposed completion or reco 1. MIRU PU. 2. Tag cement at 3940' 3. Circulate plugging mud from 39 4. Spot Yates plug from 2950'-275 5. Circulate plugging mud from 27 6. Spot 10-3/4 shoe plug from 1700 7. Circulate plugging mud from 25 8. Rig down pulling unit. 9. Cut off wellhead and install mar 10. Remove anchors and debris	PLUG AND ABANDON REMEDIAL CHANGE PLANS COMMENC MULTIPLE COMPL CASING/CE OTHER: OTHER: eted operations. (Clearly state all pertinent details rk). SEE RULE 19.15.7.14 NMAC. For Multipompletion. 40' to 2950' ti 0'. WOC and Tag. d 50' to 1700'. d 0' to surface O' to surface	E DRILLING OPNS. P AND A
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE	TITLEProduction Engine	er DATE <u>1/21/2019</u>
Type or print name <u>Vake Perry</u> E-mail address: <u>Jake Perry@oxy.com</u> PHONE: <u>713-215-7546</u> For State Use Only		
APPROVED BY: Xerve Conditions of Approval (if any):	ortner TITLE Compliance	Officer A DATE 1-23-19





GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.