Form 3160-5 (June 2015) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well O Oil Well Gas Well Other 2. Name of Operator CONOCOPHILLIPS COMPANY Contact: RHONDA ROGERS E-Mail: rogerrs@conocophillips.com				
			3b. Phone No. (include area code) Ph: 432-688-9174	HOBBON ANAR Phyloratory Area
			ey Description)	MAR: Count 2013 prish, State
			Sec 17 T17S R32E SWSE 1140FSL 2310FEL	
	Contact: RHONDA ROGERS all: rogerrs@conocophillips.com 3b. Phone No. (include area code) Ph: 432-688-9174			

CK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT,

TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	□ Water Shut-Off	
Notice of Intent	Alter Casing	Hydraulic Fracturing	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	C Recomplete	🛛 Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	Drilling Operations	
	Convert to Injection	Plug Back	Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

CONOCOPHILLIPS COMPANY WOULD LIKE TO DHC THIS WELLBORE PER DHC-4680.

PLAN IS TO PULL RODS & TBG, DRILL OUT CBP @ 4787', SPOT ACID TO CLEAN PERFS, DRILL OUT CBP @ 5304', SPOT ACID TO CLEAN PERFS, RIH W/TBG & SET SN @ 7005' AND RIH W/RODS AND PUMP & SPACE OUT.


ATTACHED IS THE CURRENT/PROPOSED WELLBORE SCHEMATIC

14. I hereby certify that t	he foregoing is true and correct. Electronic Submission #443034 verific For CONOCOPHILLIPS CO Committed to AFMSS for processing by PR	MPÁNY	, sent to the Hobbs			
Name (Printed/Typed)		Title	STAFF REGULATORY TECHNICIAN			
Signature	(Electronic Submission)	Date	11/07/2018			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By/S	/ Jonathon Shepard	T	troleum Engineer	FEBate 1 3 2019		
certify that the applicant ho	ny, are attached. Approval of this notice does not warran or ids legal or equitable title to those rights in the subject lease licant to conduct operations thereon.		rlsbad Field Office			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						
(Instructions on page 2) ** BLM REVISED **						



CURRENT SCHEMATIC

RUBY FEDERAL 02



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Workover/Deepening of a Well

- <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,100 feet, a 3M system for a well not deeper than 13,600 feet, or a 5M system for a well not deeper than 22,700 feet (all depths are for measured well depth).
- 3. <u>Cement</u>: Notify BLM if cement fails to circulate.

• • • •

- 4. <u>Subsequent Reporting</u>: Within 30 days after work is completed, file a Subsequent Report (Form 3160-5) to BLM. The report should give in detail the manner in which the work was carried out. <u>Show date work was completed</u>. If producing a new zone, submit a Completion Report (Form 3160-4) with the Subsequent Report.
- 5. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.
- If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken: From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted.