

Submit 1 Copy To Appropriate District Office <u>District I</u> – (575) 393-6161	State of New Mexico Energy, Minerals and Natural Resources		WELL API NO.	Form C-103 Revised July 18, 2013 30-025-23089
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87605	OIL CONSERVATION DIVISION 1220 South St. France Dr. Santa Fe, NM 7505 2119 ICES AND REPORTS ON WELLS		5. Indicate Type of Lease STATE FEE	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BOOM OF A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR COM			7. Lease Name or Unit Agreement Name Maxwell	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well SWD			8. Well Number	#002
2. Name of Operator Pogo Oil & Gas Operating			9. OGRID Number 372000	
3. Address of Operator P.O. Box 3217 Hobbs, NM 88240	D		10. Pool name or Wildcat Wolfcamp, Penn, Miss. Devonian	
4. Well Location				
Unit Letter E West line	2310feet from the	NorthI	ine and990	feet from the
Section 06 Township 13S Range 38E NMPM LEA County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO				
PERFORM REMEDIAL WORK PLUG AND ABANDON				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI		PANDA
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	Т ЈОВ 🗌	
CLOSED-LOOP SYSTEM		OTHER:		Ľ1
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion. 1. Test anchors				
2. RU WSU. NU BOP. Unseat pkr and TOH w/2 7/8" pc tbg.				
3. RU WL. Run gauge ring to 9549'. Run and set CIBP @9549' w/WL dump 35' class H cement on top of CIBP. WOC 4 hrs and tag. 4. TIH w/ 2-7/8" tbg, circulate hole w/ 10# gelled brine.				
5. TOH, RU wireline, perf 5-1/2" csg 2 squeeze holes @ 7000". 6. TIH w/pkr&tbg. Pump 50sxs Class H cmt, 50 in & 50 out. See Attached				
6. TIH w/pkr&tbg. Pump 50sxs Class H cmt, 50 in & 50 out. 7. Perf 2 holes @ 4576', Squeeze w/50sxs class C cmt.				
7. Perf 2 holes @ 3100', Squeeze w/50sxs class C cmt.			Conditions of Approval	
8. Perf 2 holes @ 2300', Squeeze w/50sxs class C cmt.				
9. Perf 2 holes @ 425', Squeeze w/50sxs class C cmt. and cement to surface.				
10. Put 5sxs @ surface. Install pre-made dry hole marker. 4" A:a. 4' abuve ground marker 11. Cut off well head (after NB BOP), RD, cut anchors, clean location, and move out.				
12. Rehab within 90 days per NMOCD & surface owners requirements.				
P.S. No earthern pit, all fluids will be contained in steel pit & hauled off to approved disposal facility.				
Spud Date:	Rig Release	Date:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE LA General TITLE Boulucton Mange DATE 3/28/19				
Type or print nameM.Y. Merchant E-mail address:mymerch@penrocoil.com PHONE: _575-492-1236 For State Use Only				
APPROVED BY: <u>Kerry Former</u> TITLE <u>Compliance</u> Office A DATE <u>4-1-19</u> Conditions of Approval (if any):				
Conditions of Approval (if any):	me IIILE U	mpuance Office	<u>~ ┌┐</u> DA	

;





GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.