

HOBBS OCD

APR 0 8 2019

Submit One Copy To Appropriate District	State of New Mexic RECEIVED Form C-103			
Office District I	Energy, Minerals and Natu		Rev	vised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II	OII CONSERVATION	DIVISION	WELL API NO. 32-025-0	27569
811 S First St., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Le	ase
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	000 Rio Brazos Rd , Aztec, NM 87410		STATE 6. State Oil & Gas Lea	FEE X
1220 S St Francis Dr , Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Uni	t Agreement Name
			SOUTH HOBBS (GSA) UNIT	
PROPOSALS.) 1. Type of Well: Gas Well Other			8. Well Number 3	
2. Name of Operator OCCIDENTAL PERMIAN LTD.			9. OGRID Number 157984	
3. Address of Operator			10. Pool name or Wild	
HCR 1 BOX 90, DENVEL CITY, TEXAS, 79323			H0885 (G	5A)
4. Well Location Unit Letter : 1980 feet from the S line and 560 feet from the W line				
Section 34 Township 188 Range 38E NMPM USA County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3635 (KB) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
NOTICE OF INTENTION TO: SUBS			SEQUENT REPOI	ERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A				
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	. 108 🔲	
OTHER: Location is ready for OCD inspection after P&A				
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
BELOW OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OUARTER/OUARTER LOCATION OR				
<u>Unit Letter, Section, Township, and Range. All Information has been welded or</u>				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)				
All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.				
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well				
location, except for utility's distribution infrastructure.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE QUI	TITLE	DOST. SHECIAL	AST DAT	TE 4/8/19
SIGNATURE OF LAND TYPE OR PRINT NAME REX UNFOR State Use Only	LICHE-MAIL:	REX_whate	OXY COM PHO	NE: <u>806 - 215-7</u> 135
APPROVED BY: Kerry	ritherTITLE_(impliance	Officer A DA	TE 4-8-19





Rex Ulrich
construction specialist
OXY PERMIAN, LTD.
(806) 215-7135 Cell
rex_ulrich@oxy.com

Cheap labor is not skilled... Skilled labor is not cheap