

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-34788
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	NEW MEXICO 'EA' STATE
8. Well No.	1
9. Pool Name or Wildcat	HOBBS; ABO, NORTHWEST
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3672'

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITS (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>A</u> : <u>410</u> Feet From The <u>NORTH</u> Line and <u>610</u> Feet From The <u>EAST</u> Line Section <u>24</u> Township <u>18S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3672'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☒ C/O, ADD PERFS, ACIDIZE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-20-06: MIRU. REL TAC.  
4-21-06: TIH W/BIT TO 6706. PUH OUT OF WINDOW TO 6544. (WINDOW 6620-6629).  
4-24-06: TIH TO 7643. TAG FILL. PUMP 1500 GALS 20% NEFE. POH ABOVE WINDOW. PUMP 30 BBLS TO FLUSH WELL.  
4-25-06: TAG CIBP @ 6633. PUH TO 6609. KNOCK OUT CIBP. PUSH DN TO 6975. TAG FILL. TAG CIBP @ 6975. PUSH DN TO 7567. PUH ABOVE WINDOW TO 6609'.  
4-26-06: POH W/WS.  
4-27-06: PERF 7076-85, 7092-99, 7124-30, 7132-36, 7146-54, 7198-7212, 7218-24, 7248-52, 7294-7302, 7310-20, 7384-92, 7416-18, 7452-56, 7460-66, 7520-22, 7543-54.  
4-28-06: TIH W/PKR, TBG & WS. TAG PBTD @ 7567. PUH TO 7055. SET PKR.  
5-01-06: ACIDIZE PERFS 7076-7554 W/3500 GALS 20% HCL. PUH & SET PKR @ 7055. RU SWAB.  
5-02-06: SWB.  
5-03-06: REL PKR. TIH W/BPMAJ, PERF SUB, SN, 45 JTS, TAC, & TBG.  
5-04-06: TIH W/PROD TBG. 230 JTS EOT @ 7528. TIH W/PUMP & RODS. LOAD & TEST.  
5-05-06: HANG WELL ON. RIG DOWN. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Pinkerton

TITLE Regulatory Specialist

DATE 5/9/2006

TYPE OR PRINT NAME Denise Pinkerton

Telephone No. 432-687-7375

(This space for State Use)

APPROVED Hay W. Wink  
CONDITIONS OF APPROVAL, IF ANY: TITLE

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

MAY 12 2006