Office District I - (575) 393-6161				Form C-103
	Energy, Minerals and N	latural Resources	WELL ADINO	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283			WELL API NO. 30-025-30236	
811 S. First St., Artesia, NM 88210	OIL CONSERVATI		5. Indicate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. I		STATE [FEE 🏻
	Santa Fe, NM	I 87505		
1220 S. St. Francis Dr., Santa Fe, NM 87505			313857	
SUNDRY NOTION	CES AND REPORTS ON WE	LLS	7. Lease Name or Ur	nit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OF	REVERSACK TO A	WEST DOLLAR	HIDE QUEEN SAND
PROPOSALS.)	ATION FOR PERMIT" (FORM C-10	1) 10 kg 6 -	UNIT	
1. Type of Well: Oil Well	Gas Well 🔲 Other	See Oc	N/-11 N	116
District IV — (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well: Oil Well		of policy	8. Well Number	115
2. Name of Operator RAM ENERGY LLC	R	SEP O OCL	9. OGRID Number	309777
3. Address of Operator		Elle	10. Pool name or Wi	
2100 S. UTICA AVE., SUITE 1	75, TULSA, OK 74114	ED		QUEEN (018810)
4. Well Location			<u> </u>	
Unit LetterE12	10feet from the _WEST_	line and1400	feet from the	NORTH_line
Section 05	Township 25S	Range 38E	NMPM	LEA County
	11. Elevation (Show whether			
	3136' KB			
12. Check A	ppropriate Box to Indicate	Nature of Notice,	Report or Other Da	ıta ·
NOTICE OF IN	TENTION TO:	■ CHR	SEQUENT REPO	NDT ()E.
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		TERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI		AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	<u></u>	
DOWNHOLE COMMINGLE	_		_	
·	_			_
OTUED:	1 1	I ATUED.		1 1
OTHER: 13. Describe proposed or complete.	eted operations. (Clearly state:	OTHER:	l give pertinent dates, i	ncluding estimated date
13. Describe proposed or comple	eted operations. (Clearly state : k). SEE RULE 19.15.7.14 NN	all pertinent details, and		
13. Describe proposed or comple	k). SEE RULE 19.15.7.14 NM	all pertinent details, and		
13. Describe proposed or comple of starting any proposed wor proposed completion or reco	k). SEE RULE 19.15.7.14 NM mpletion.	all pertinent details, and		
Describe proposed or complete of starting any proposed work proposed completion or recommendate. NOTIFY NMOCD 24 HRS.	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU.	all pertinent details, and		
 Describe proposed or completed of starting any proposed work proposed completion or recompletion. NOTIFY NMOCD 24 HRS. MIRU. ND WH, NU BOPE. 	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU.	all pertinent details, and IAC. For Multiple Con	npletions: Attach welli	
 Describe proposed or completed of starting any proposed work proposed completion or reconstruction. NOTIFY NMOCD 24 HRS. MIRU. ND WH, NU BOPE. SET CIBP@3500' AND SPORTS. 	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEN	all pertinent details, and IAC. For Multiple Con	npletions: Attach welli	
 Describe proposed or completed of starting any proposed work proposed completion or recompletion. NOTIFY NMOCD 24 HRS. MIRU. ND WH, NU BOPE. 	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CENTAND TEST CASING.	all pertinent details, and IAC. For Multiple Con	npletions: Attach welli	
13. Describe proposed or complete of starting any proposed work proposed completion or reconstruction. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPA. 4. CIRCULATE 9.5 PPG MLF. 5. SPOT 35SX OF CLASS "C". 6. SPOT 25SX OF CLASS "C".	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEMENT FROM 2725'-2405' CEMENT FROM 1250'-1100' CEMENT FROM 1250'-1100' CEMENT FROM 1250'-1100' CEMENT FROM 1250'-1100'	all pertinent details, and IAC. For Multiple Condens of the Martin of th	npletions: Attach welli 50'. (PERFS) ES/B.SALT) LT)	bore diagram of
13. Describe proposed or complete of starting any proposed work proposed completion or reconstruction. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPORT SET CIPP@3500' AND SET CIPP@350	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEM AND TEST CASING. CEMENT FROM 2725'-2405' CEMENT FROM 1250'-1100' CEMENT FROM 461'-SURF	all pertinent details, and IAC. For Multiple Condens of the Martin State of the Martin	npletions: Attach welli 550'. (PERFS) ES/B.SALT) LT) NT TO SURFACE. (F	bore diagram of W/SHOE/SURFACE).
13. Describe proposed or complete of starting any proposed was proposed completion or recomplete. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPORT SET CIBP@3500' AND SPORT SET CIBP. 5. SPOT 35SX OF CLASS "C" 6. SPOT 25SX OF CLASS "C" 7. SPOT 55SX OF CLASS "C" 8. CUTOFF WELLHEAD, AND	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEM AND TEST CASING. CEMENT FROM 2725'-2405' CEMENT FROM 1250'-1100' CEMENT FROM 461'-SURF	all pertinent details, and IAC. For Multiple Constant FROM 3500'-32 '. WOC&TAG. (YATIO)'. WOC&TAG. (T.SAIO) CACE. VERIFY CEME	npletions: Attach welli 550'. (PERFS) ES/B.SALT) LT) NT TO SURFACE. (F	bore diagram of W/SHOE/SURFACE).
13. Describe proposed or complete of starting any proposed work proposed completion or reconstruction. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPORT SET CIPP@3500' AND SET CIPP@350	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEM AND TEST CASING. CEMENT FROM 2725'-2405' CEMENT FROM 1250'-1100' CEMENT FROM 461'-SURF	all pertinent details, and IAC. For Multiple Constant FROM 3500'-32 '. WOC&TAG. (YATIO)'. WOC&TAG. (T.SAIO) CACE. VERIFY CEME	npletions: Attach welli 50'. (PERFS) ES/B.SALT) LT) NT TO SURFACE. (F YHOLE MARKER. TU	w/SHOE/SURFACE). URN OVER FOR
 Describe proposed or complete of starting any proposed was proposed completion or reconsistency. NOTIFY NMOCD 24 HRS. MIRU. ND WH, NU BOPE. SET CIBP@3500' AND SPORT SET CIBP@3500 AND SET CIBP@3500 AND SECLAMATION. 	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEM AND TEST CASING. CEMENT FROM 2725'-2405' CEMENT FROM 1250'-1100' CEMENT FROM 461'-SURF	all pertinent details, and IAC. For Multiple Condens of March 1988 AND INSTALL DRY	npletions: Attach welli 50'. (PERFS) ES/B.SALT) LT) NT TO SURFACE. (F YHOLE MARKER. TU	w/SHOE/SURFACE). URN OVER FOR
 Describe proposed or complete of starting any proposed was proposed completion or reconsistency. NOTIFY NMOCD 24 HRS. MIRU. ND WH, NU BOPE. SET CIBP@3500' AND SPORT SET CIBP@3500 AND SET CIBP@3500 AND SECLAMATION. 	ck). SEE RULE 19.15.7.14 NM smpletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEM AND TEST CASING. CEMENT FROM 2725'-2409' CEMENT FROM 1250'-1100' CEMENT FROM 461'-SURFICHORS 3' BELOW SURFAC	all pertinent details, and IAC. For Multiple Condens of March 1988 AND INSTALL DRY	npletions: Attach welli 50'. (PERFS) ES/B.SALT) LT) NT TO SURFACE. (F YHOLE MARKER. TU	w/SHOE/SURFACE). URN OVER FOR
13. Describe proposed or complete of starting any proposed was proposed completion or reconsistency. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPORT SET CIBP@3500 AND SECLASS "C" 8. CUTOFF WELLHEAD, AN RECLAMATION. CLOSED LOOP CONTAIN	Ek). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEM AND TEST CASING. CEMENT FROM 2725'-2409' CEMENT FROM 1250'-1100' CEMENT FROM 461'-SURFICHORS 3' BELOW SURFACEMENT SYSTEM WILL BE U	all pertinent details, and IAC. For Multiple Constant FROM 3500'-32 Y. WOC&TAG. (YATI YACE. VERIFY CEME E AND INSTALL DR'SED FOR FLUIDS.	npletions: Attach welli 50'. (PERFS) ES/B.SALT) LT) NT TO SURFACE. (F YHOLE MARKER. TU	w/SHOE/SURFACE). URN OVER FOR
 Describe proposed or complete of starting any proposed was proposed completion or reconsistency. NOTIFY NMOCD 24 HRS. MIRU. ND WH, NU BOPE. SET CIBP@3500' AND SPORT SET CIBP@3500 AND SET CIBP@3500 AND SECLAMATION. 	ck). SEE RULE 19.15.7.14 NM smpletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEM AND TEST CASING. CEMENT FROM 2725'-2409' CEMENT FROM 1250'-1100' CEMENT FROM 461'-SURFICHORS 3' BELOW SURFAC	all pertinent details, and IAC. For Multiple Constant FROM 3500'-32 Y. WOC&TAG. (YATI YACE. VERIFY CEME E AND INSTALL DR'SED FOR FLUIDS.	npletions: Attach welli 50'. (PERFS) ES/B.SALT) LT) NT TO SURFACE. (F YHOLE MARKER. TU	w/SHOE/SURFACE). URN OVER FOR
13. Describe proposed or complete of starting any proposed was proposed completion or reconsistency. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPORT SET CIBP@3500 AND SECLASS "C" 8. CUTOFF WELLHEAD, AN RECLAMATION. CLOSED LOOP CONTAIN	Ek). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEM AND TEST CASING. CEMENT FROM 2725'-2409' CEMENT FROM 1250'-1100' CEMENT FROM 461'-SURFICHORS 3' BELOW SURFACEMENT SYSTEM WILL BE U	all pertinent details, and IAC. For Multiple Constant FROM 3500'-32 Y. WOC&TAG. (YATI YACE. VERIFY CEME E AND INSTALL DR'SED FOR FLUIDS.	npletions: Attach welli 50'. (PERFS) ES/B.SALT) LT) NT TO SURFACE. (F YHOLE MARKER. TU	w/SHOE/SURFACE). URN OVER FOR
13. Describe proposed or complete of starting any proposed work proposed completion or reconstruction of the proposed completion or reconstruction of the proposed completion or reconstruction. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPOPE. 4. CIRCULATE 9.5 PPG MLF. 5. SPOT 35SX OF CLASS "C". 6. SPOT 25SX OF CLASS "C". 7. SPOT 55SX OF CLASS "C". 8. CUTOFF WELLHEAD, AN RECLAMATION. CLOSED LOOP CONTAIN. Spud Date:	Rig Release	all pertinent details, and IAC. For Multiple Confident FROM 3500'-32 '. WOC&TAG. (YATI WOC&TAG. (T.SAI ACE. VERIFY CEME E AND INSTALL DR'SED FOR FLUIDS.	ES/B.SALT) ES/B.SALT) ES/B.SALT) ES/B.SALT) ES/B.SALT) ES/B.SALT ES/B.S	bore diagram of W/SHOE/SURFACE).
13. Describe proposed or complete of starting any proposed was proposed completion or reconsistency. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPORT SET CIBP@3500 AND SECLASS "C" 8. CUTOFF WELLHEAD, AN RECLAMATION. CLOSED LOOP CONTAIN	Rig Release	all pertinent details, and IAC. For Multiple Confident FROM 3500'-32 '. WOC&TAG. (YATI WOC&TAG. (T.SAI ACE. VERIFY CEME E AND INSTALL DR'SED FOR FLUIDS.	ES/B.SALT) ES/B.SALT) ES/B.SALT) ES/B.SALT) ES/B.SALT) ES/B.SALT ES/B.S	w/SHOE/SURFACE). URN OVER FOR
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting and proposed work proposed complete or recomplete of the starting and proposed work proposed complete of the starting and proposed complete or recomplete or	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEM AND TEST CASING. CEMENT FROM 2725'-2405' CEMENT FROM 1250'-1100' CEMENT FROM 461'-SURFICHORS 3' BELOW SURFACEMENT SYSTEM WILL BE UTTO Rig Release bove is true and complete to the	all pertinent details, and IAC. For Multiple Condition MENT FROM 3500'-32 MENT FROM	npletions: Attach welling to the second state of the second state	w/shoe/surface). URN OVER FOR Attached S of Approval
13. Describe proposed or complete of starting any proposed work proposed completion or reconstruction of the proposed completion or reconstruction of the proposed completion or reconstruction. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPOPE. 4. CIRCULATE 9.5 PPG MLF. 5. SPOT 35SX OF CLASS "C". 6. SPOT 25SX OF CLASS "C". 7. SPOT 55SX OF CLASS "C". 8. CUTOFF WELLHEAD, AN RECLAMATION. CLOSED LOOP CONTAIN. Spud Date:	ck). SEE RULE 19.15.7.14 NM impletion. BEFORE MIRU. OT 25SX OF CLASS "C" CEM AND TEST CASING. CEMENT FROM 2725'-2405' CEMENT FROM 1250'-1100' CEMENT FROM 461'-SURFICHORS 3' BELOW SURFACEMENT SYSTEM WILL BE UTTO Rig Release bove is true and complete to the	all pertinent details, and IAC. For Multiple Confident FROM 3500'-32 '. WOC&TAG. (YATI WOC&TAG. (T.SAI ACE. VERIFY CEME E AND INSTALL DR'SED FOR FLUIDS.	npletions: Attach welling to the second state of the second state	w/shoe/surface). URN OVER FOR Attached S of Approval
13. Describe proposed or complete of starting any proposed was proposed completion or reconsistency. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPORT SET CIBP@3500 AND SET CIBP@3500	Rig Release bove is true and complete to the	ALC. For Multiple Condition MENT FROM 3500'-32 MENT FROM 3500'-3	See	w/SHOE/SURFACE). URN OVER FOR Attached S of Approval
13. Describe proposed or complete of starting any proposed work proposed completion or reconsistency. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPORT SET CIBP@3500 AND SET CI	Rig Release bove is true and complete to the TITLE TERSON E-mail address: M.	ALL DESCRIPTIONS MANA PATTERSON@RAMI	See Condition and belief. AGERDATE08. ENERGY.NET_PHON	w/SHOE/SURFACE). URN OVER FOR Attached S of Approval /26/19
13. Describe proposed or complete of starting any proposed work proposed completion or reconsistency. 1. NOTIFY NMOCD 24 HRS. 2. MIRU. ND WH, NU BOPE. 3. SET CIBP@3500' AND SPORT SET CIBP@3500 AND SET CI	Rig Release bove is true and complete to the	ALL DESCRIPTIONS MANA PATTERSON@RAMI	See Condition and belief. AGERDATE08. ENERGY.NET_PHON	w/SHOE/SURFACE). URN OVER FOR Attached S of Approval /26/19

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #115 CURRENT

Created: Updated:	08/26/19	By: <u>LEE R.</u> By:	Well #: API	115 30-025-30	0236
Lease:	WEST DOOLARH	IDE QUEEN SAND UNIT	Unit Ltr.:		ec. 5
Field:		UEEN	TSHP/Rng:	25S-T3	8E
Surf. Loc.:	1210' FW	L & 1400' FNL	Pool Code:	OGR	RID: 309777
Bot. Loc.:					
County:	LEA	St.: NM	Directions:		
Status:			-		
Surface Cas Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	8-5/8" 24# 411' 250 YES SURFACE 12-1/4"				
FORMATION T.Salt B. Salt	TOPS 1200' 2505'				
Intermediate Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	5-1/2" 15.5# 3920' 900 YES SURFACE 7-7/8"		Que	en: 3588'-3614'((OA)

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #115 PROPOSED

Created: Updated: Lease: Field: Surf. Loc.: Bot. Loc.: County: Status:	Q	By: LEE R. By: IDE QUEEN SAND UNIT UEEN L & 1400' FNL St.: NM	Well #: API Unit Ltr.: TSHP/Rng: Pool Code: Directions:	115 30-025-30236 E Sec. 5 25S-T38E OGRID: 309777
Surface Cas Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	8-5/8" 24# 411' 250 YES SURFACE 12-1/4"			POT 55SX OF CMT FROM 461'-SURFACE. ERIFY. (FW/SHOE/SURFACE)
FORMATION T.Salt B. Salt	TOPS 1200' 2505'		MLF SI	POT 25SX OF CMT FROM 1250'-1100'. OC&TAG. (T.SALT) POT 35SX OF CMT FROM 2725'-2405'. OC&TAG. (YATES/B.SALT)
Intermediate Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	5-1/2" 15.5# 3920' 900 YES SURFACE 7-7/8"			ET CIBP@3500' AND SPOT 25SX ON TOP ROM 3500'-3250'.(PERFS) ueen: 3588'-3614'(OA)

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.