

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-2833
811 S. First St., Alamogordo, NM 88210
District III - (505) 344-6178
1000 Rio Bravo Blvd., Aztec, NM 87401
District IV - (505) 476-2800
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-41601
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Northeast Drinkard Unit (NEDU) [22503]
8. Well Number 536
9. OGRID Number 873
10. Pool name or Wildcat Eunice; B-T-D, North [22900]
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3443' GL

SUMMARY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator Apache Corporation	
3. Address of Operator 303 Veterans Airpark Lane, Suite 1000 Midland, TX 79705	
4. Well Location Unit Letter A : 140 feet from the North line and 475 feet from the East line Section 15 Township 21S Range 37E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3443' GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Apache would like to add Drinkard pay and acidize, as follows:

1. POOH with rods and 2-7/8" production tubing.
2. PU workstring and RIH with nitrogen unit. Clean out wellbore to PBTD at 6904'. POOH.
3. RIH with wireline and perforate Blinberry, Tubb and Drinkard formation at 5710'-6620'. POOH.
4. RIH w/ work string and 5-1/2" treating packer. Acidize Blinberry-Tubb-Drinkard interval with 10,000 gallons 15% HCL acid. POOH.
5. RIH with 2-7/8" production tubing and seat nipple set at ~6705'.
6. Return well to production.

Spud Date:

2/20/2014

Rig Release Date:

2/25/2014

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Reesa Fisher

TITLE Sr. Staff Reg Analyst

DATE 8/26/2019

Type or print name Reesa Fisher

E-mail address: Reesa.Fisher@apachecorp.com

PHONE: (432) 818-1062

For State Use Only

APPROVED BY:

Kerry Foster

TITLE


C.O. A

DATE


9-16-19
9-6-19

Conditions of Approval (if any)


Current Wellbore Diagram




Current Wellbore Diagram



Proposed Wellbore Diagram (Proposed Changes in Yellow)



Proposed Wellbore Diagram (Proposed Changes in Yellow)



Proposed Wellbore Diagram (Proposed Changes in Yellow)

