## UNITED STATES OF THE INTEREST SHAPE STATES. J BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON VEICED Hobbs FORM OMB N Expires: J OMN N NMNM02127B

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. 8910064550	
1. Type of Well				8. Well Name and No. LEA UNIT SWD 08	8
Oil Well Gas Well Other: INJECTION					<del></del> -
I. Type of Well  ☐ Oil Well ☐ Gas Well ☑ Other: INJECTION  2. Name of Operator LEGACY RESERVES OPERATING LÆ-Mail: jsaenz@legacylp.com  OCT 17 2019				9. API Well No. 30-025-02431-00-S1	
3a. Address 303 W WALL SUITE 1600 MIDLAND, TX 79702  3b. Phone No. (inclu Ph: 432-689-520			EIVED	10. Field and Pool or Exploratory Area LEA SWD	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, S	itate
Sec 12 T20S R34E NWNE 810FNL 1980FEL				LEA COUNTY, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize ☐ 1	Deepen	☐ Production (Start/Resume)		■ Water Shut-Off
_	☑ Alter Casing ☐	Hydraulic Fracturing	☐ Reclama	ation	■ Well Integrity
Subsequent Report	Casing Repair	New Construction	☐ Recomplete		□ Other
☐ Final Abandonment Notice	☐ Change Plans ☐ 1	Plug and Abandon	☐ Temporarily Abandon		
	☐ Convert to Injection ☐ I	Plug Back	■ Water Disposal		
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  MIRU. POH with injection tubing and packer and laid down. PU 6-1/8" bit and tagged up at surface. Changed to 6" bit and tagged at 819'. Cleaned out to 847' getting returns of formation, scale, and metal, bit bouncing. Changed over to 4-3/4" bit and tagged up 845'. Cleaned out to 847' no change. Changed over to 2-7/8" notched collar, same results. RIH with impression block. Impression block shows two deep marks directly across from each other (180 degrees), showing casing collapsed. RIH with 6" tapered mill and tagged at 847'. Mill plugged off. RIH with 6" shoe and tagged at 847'. Work down to 849' and shoe plugged off. Worked 6" mill at surface. RIH with 6-1/8" bit and tagged at 844'. Washed down to 849.5', metal in returns. Lost circulation and POOH.					
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #484003 verified by the BLM Well Information System  For LEGACY RESERVES OPERATING LP, sent to the Hobbs  Committed to AFMSS for processing by PRISCILLA PEREZ on 09/19/2019 (19PP2790SE)					
Name (Printed/Typed) JOHN SAE	Title OPERAT	Title OPERATIONS ENGINEER			
Signature (Electronic S	Date 09/19/20	Date 09/19/2019			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By  Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		or Jo	<b>Dted fo</b> nathon Si	r Record hepard d Office	OCIJateO 8 2019
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					

(Instructions on page 2)

\*\*BLM REVISED \*\* BLM REVI

## Additional data for EC transaction #484003 that would not fit on the form

## 32. Additional remarks, continued

RIH with 6-1/8" bit and tagged at 754'. Washed down to 849', sand, formation, red beds and metal in

returns.
Run casing inspection log. Tagged at 510'. Logged 510' to surface. No issues identified.
RIH with 2-7/8" notched collar and tagged at 510'. Tubing plugged off.
RIH with magnet tag at 328' and work down to 360', no recovery.
RIH with 6" shoe and tagged at 360'. Worked down to 450' and shoe plugged off. POOH.
Pumped 50 sx Class C with 2% CaCl and POL-E-Flake. Displaced with 27 bbls.
RIH with 6-1/8" bit and tagged at 727'. Drilled cement to 845'. Washed sand and formation to 850'.
RIH with 6-1/8" concave mill and tagged at 600'. Washed sand and formation to 630'. Tubing plugged.
RIH with 6-1/8" concave mill and tagged at 437'. Washed sand and formation to 670'. Progress

stopped. POOH.
Pumped 100 sx Class C with 3% CaCl. Displaced with 27 bbls.

RIH with 6-1/8" bit and tagged cement stringers from 500'-690'. Drilled solid cement from 690' to

Washed sand and formation to 852'. POH.
RIH with 6-1/8" bit and tagged at 450'. Washed sand and formation down to 670'. Progress stopped.
RIH with 6-1/8" shoe and tagged at 670'. Shoe plugged off, no progress. Plugged with large piece of formation and deep scarring on outside of shoe. Lay down work string.

Attempt to pump into well. Pressured up to 2000 psi immediately and held.

Next step. We will be switching to 24hr operation to finish installing liner.

