Submit 1 Copy To Appropriate District	State of New M	exico		Form C-103
Office <u>District I</u> – (575) 393-6161			Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240	625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210			<u>30-025-44207</u>	
<u>District III</u> - (505) 334-6178	istrict III - (505) 334-6178 1220 South St. Francis Dr.		5. Indicate Type of STATE	FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460	000 Rio Brazos Rd., Aztec, NM 87410 istrict IV - (505) 476-3460 Santa Fe, NM 87505		6. State Oil & Gas I	
1220 S. St. Francis Dr., Santa Fe, NM 87505		320052		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name West Eumont Unit	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number	#211
2. Name of Operator Forty Acres Energy, LLC			9. OGRID Number	
			371416	
3. Address of Operator			10. Pool name or Wildcat	
11757 Katy Freeway, Suite 1000. Houston, TX 77079			7 Rivers - Queen	
4. Well Location				
Unit Letter B :	1185feet from theN		_1345feet from th	
Section 02	Township 21S	Range 35E	NMPM	County Lea
	11. Elevation (Show whether DI 3563 (1
5505 OL				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
				AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	т јов 🔲	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				_
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
	•			
1. Shut wells in 48	hours prior to conducting the	ne step rate test.		
2. Using a pump truck equipped with chart recorder and digital monitors, we will begin injecting at 0.5				
bbl/minute and record pressure.				
3. Bottom hole pressures gauge will be used via wireline				
4. We will then step the rate up to 1 bpm, 2 bpm, 3 bpm, etc. until Formation Parting Pressure is				
reached. 5. S.R.T. results will be provided to the OCD following the test.				
5. S.R.T. results w	all be provided to the OCD is	bilowing the test.		
	s.			
	· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·	
· · · · · · · · · · · · · · · · · · ·	<u> </u>	[· · · · · · · · · · · · · · · · · · ·	1
Spud Date:	Rig Release D	ate:		
	J			J
				<u> </u>
I hereby certify that the information a	-	• •		
	/			
SIGNATURE (e. Han		Ensincer	DATE	1.29.2020
SIGNATURE <u>G</u> Type or print name <u>Gracest</u> For State Use Only APPROVED BY: <u>Conditions of Approval (Fany)</u>	(11 DD			
Type or print name _ Coraccet	Johnson E-mail addres	is: garrate f	acregyus. PHON	NE: <u>837-706-00</u> 57
For State Use Only				
ADDOLVED DV.	TITLE	Petroleum E	ngineer DATE	alzolanon
Conditions of Approval (Hany):	IIILE	<u> </u>	DATE	0117010000
Source of Apploval (n any).				

- -----