

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised August 1, 2011

|   |
|---|
| WELL API NO.<br>30-025-43073  |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.  |
| 7. Lease Name or Unit Agreement Name<br>North Hobbs (G/SA) Unit                                     |
| 8. Well Number: 680   |
| 9. OGRID Number: 157984   |
| 10. Pool name or Wildcat<br>Hobbs (G/SA)  |

HOBBS OCD  
JAN 9 2020  
RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other: -----

2. Name of Operator  
Occidental Permian Ltd.

3. Address of Operator  
P.O. Box 4294, Houston, 77210-4294

4. Well Location  
Unit Letter H : 216 feet from the N line and 537 feet from the E Line  
Section 24 Township 18-S Range 37-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3669' (GL)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK  PLUG AND ABANDON
- TEMPORARILY ABANDON  CHANGE PLANS
- PULL OR ALTER CASING  MULTIPLE COMPL
- DOWNHOLE COMMINGLE

OTHER:

SUBSEQUENT REPORT OF:

- REMEDIAL WORK  ALTERING CASING
- COMMENCE DRILLING OPNS.  P AND A
- CASING/CEMENT JOB

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.


1. POOH with injection equipment
2. RIH with CICR and set it at +/- 4350'
3. RU Cementing Co and cement sqz existing perfs, RD Cementing Co.
4. RIH with 6-1/4" bit and DO CICR, cement and CIBP, continue CO to PBTD, POOH with bit
5. RU WL and selectively perf from 4452' to 4564' (Gross interval), POOH and RD WL
6. RIH with PPI tool and acid stimulate new perfs using ~ 7200 gal of 15% HCL, POOH and LD PPI Tool
7. RIH with injection equipment.
8. RDMO.
9. Place well back on injection

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Production Engineer DATE 1/29/2020

Type or print name Carlos Restrepo E-mail address carlos\_restrepo@oxy.com PHONE: 713-366-5147

For State Use Only

APPROVED BY:  TITLE CD A DATE 2-10-20  
Conditions of Approval (if any):

Additional Data that would not fit on the form.