Form	3160-5
(June	2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM A	PPROVED
OMB NO	. 1004-0137
Expires: Jan	uary 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals					NMLC062300 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 1					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well Gas Well	ner	Kyr	CEB 1	VED	Well Name and No. Multiple—See Attached		
Name of Operator CHEVRON USA INCORPORA	Contact: ATED E-Mail: LBECERR	LAURA BECI A@CHEVRON	RRA COM		API Well No. Multiple—See Attached		
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706 3b. Phone No. (include area code) Ph: 432-687-7665)	10. Field and Pool or Exploratory Area WC025G06S253206M-BONE SPRING WOLFCAMP		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Multiple-See Attached					LEA COUNTY, NM		
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION			TYPE O	F ACTION			
■ Notice of Intent	☐ Acidize	☐ Dee	oen	□ Producti	on (Start/Resume)	■ Water Shut-Off	
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	□ Reclama	tion	□ Well Integrity	
☐ Subsequent Report	□ Casing Repair	□ New	Construction	□ Recomp	lete	Other	
☐ Final Abandonment Notice	□ Change Plans	Plug	and Abandon	□ Tempora	rarily Abandon Onshore Order Varia		
	☐ Convert to Injection	☐ Plug	g Back		isposal		
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Chevron respectfully requests a variance from the Onshore Order 2 where it states "A full BOP Test shall be performed: when initially installed and whenever any seal subject to test pressure is broken." We propose to break test if able to finish the next hole section within 21 days of the previous full BOP test. A break test will not be performed on our last production section. A break test will only be performed on operations where BLM documentation states a 5M or less BOP can be utilized. Summary of changes is attached. This request applies to the following wells on this pad:							
14. I hereby certify that the foregoing is	Electronic Submission #	USA INCORP	DRÅTED, sent to	the Hobbs	_	···	
Name (Printed/Typed) LAURA BI	ECERRA .		Title REGUL	ATORY SPE	CIALIST		
Signature (Electronic S	Submission)		Date 12/17/2	019			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	SE		
_Approved By_NDUNGU KAMAU		TitlePETROLEUM ENGINEER Date 01/13		Date 01/13/2020			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Hobbs				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Additional data for EC transaction #496247 that would not fit on the form

Wells/Facilities, continued

Agreement NMLC062300	Lease NMLC062300	Well/Fac Name, Number CO YETI 15 22 FED COM 0051H	API Number 30-025-45531-00-X1	Location Sec 15 T25S R32E NWNE 10FNL 1335FEL
NMLC062300	NMLC062300	CO YETI 15 22 FED COM 0052H	30-025-45534-00-X1	32.137733 N Lat, 103.658531 W Lon Sec 15 T25S R32E NENE 10FNL 1310FEL 32.137733 N Lat, 103.658455 W Lon
NMLC062300	NMLC062300	CO YETI 15 22 FED COM 0053H	30-025-45533-00-X1	Sec 15 T25S R32E NENE 10FNL 1285FEL 32.137733 N Lat. 103.658371 W Lon
NMLC062300	NMLC062300	CO YETI 15 22 FED COM 0054H	30-025-45537-00-X1	Sec 15 T25S R32E NENE 10FNL 1260FEL 32.137733 N Lat, 103.658295 W Lon
NMLC062300	NMLC062300	CO YETI 15 22 FED COM 0055H	30-025-45535-00-X1	Sec 15 T25S R32E NENE 10FNL 1235FEL 32.137733 N Lat, 103.658211 W Lon
NMLC062300	NMLC062300	CO YETI 15 22 FED COM 0056H	30-025-45536-00-X1	Sec 15 T25S R32E NENE 10FNL 1210FEL 32 137733 N Lat, 103.658127 W Lon

32. Additional remarks, continued

CO YETI 15 22 FED COM 51H - 30-025-45531 CO YETI 15 22 FED COM 52H - 30-025-45534 CO YETI 15 22 FED COM 53H - 30-025-45533 CO YETI 15 22 FED COM 54H - 30-025-45537 CO YETI 15 22 FED COM 55H - 30-025-45535 CO YETI 15 22 FED COM 56H - 30-025-45536

Revisions to Operator-Submitted EC Data for Sundry Notice #496247

Operator Submitted

BLM Revised (AFMSS)

Sundry Type:

Lease:

NMLC062300

VARI NOI

NMLC062300

Agreement:

Operator:

CHEVRON USA INC 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432-687-7665

LAURA BECERRA REGULATORY SPECIALIST

E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665

Tech Contact:

Admin Contact:

LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665

Location:

State: County:

NM LEA

Field/Pool:

WC025G06S253206M-BONE SPR

Well/Facility:

CO YETI 15 22 FED COM 51H Sec 15 T25S R32E Mer NMP NWNE 10FNL 1335FEL

CHEVRON USA INCORPORATED

6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432.687.7100 Fx: 432-687-7221

LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665

LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665

NM LEA

WC025G06S253206M-BONE SPRING

WOLFCAMP

CO YETI 15 22 FED COM 0051H
Sec 15 T25S R32E NWNE 10FNL 1335FEL
32.137733 N Lat, 103.658531 W Lon
CO YETI 15 22 FED COM 0052H
Sec 15 T25S R32E NENE 10FNL 1310FEL
32.137733 N Lat, 103.658455 W Lon
CO YETI 15 22 FED COM 0053H
Sec 15 T25S R32E NENE 10FNL 1285FEL
32.137733 N Lat, 103.658371 W Lon
CO YETI 15 22 FED COM 0054H
Sec 15 T25S R32E NENE 10FNL 1260FEL
32.137733 N Lat, 103.658295 W Lon
CO YETI 15 22 FED COM 0055H
Sec 15 T25S R32E NENE 10FNL 1235FEL
32.137733 N Lat, 103.65821V W Lon
CO YETI 15 22 FED COM 0056H
Sec 15 T25S R32E NENE 10FNL 1210FEL
32.137733 N Lat, 103.65821V W Lon

32.137733 N Lat, 103.658127 W Lon

PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OPERATOR'S NAME: CHEVRON USA INCORPORATED LEASE NO.: NMLC0062300 COUNTY: LEA

CO YETI 15 22 FED COM 0051H

LOCATION: Section 15, T25S, R32E, NMPM SURFACE HOLE FOOTAGE: 10'/N & 1335'/E BOTTOM HOLE FOOTAGE: 100'/S & 2090'/E

CO YETI 15 22 FED COM 0052H

LOCATION: Section 15, T25S, R32E, NMPM SURFACE HOLE FOOTAGE: 10'/N & 1310'/E BOTTOM HOLE FOOTAGE: 100'/S & 2090'/E

CO YETI 15 22 FED COM 0053H

LOCATION: Section 15, T25S, R32E, NMPM SURFACE HOLE FOOTAGE: 10'/N & 1285'/E BOTTOM HOLE FOOTAGE: 100'/S & 1210'/E

CO YETI 15 22 FED COM 0054H

LOCATION: Section 15, T25S, R32E, NMPM SURFACE HOLE FOOTAGE: 10'/N & 1260'/E BOTTOM HOLE FOOTAGE: 100'/S & 1210'/E

CO YETI 15 22 FED COM 0055H

LOCATION: Section 15, T25S, R32E, NMPM SURFACE HOLE FOOTAGE: 10'/N & 1235'/E BOTTOM HOLE FOOTAGE: 100'/S & 330'/E

CO YETI 15 22 FED COM 0056H

LOCATION: Section 15, T25S, R32E, NMPM SURFACE HOLE FOOTAGE: 10'/N & 1210'/E BOTTOM HOLE FOOTAGE: 100'/S & 330'/E

ALL PREVIOUS COAs STILL APPLY

A. SPECIAL REQUIREMENT (S)

BOP Break Testing Variance (Note: For 5M BOP or less)

- While in transfer between wells, the BOPE shall be secured by the hydraulic carrier or cradle.
- Any well control event while drilling require notification to the BLM Petroleum Engineer prior to the commencement of any BOP Break Testing operations.
- A full BOP test is required prior to drilling the first deep intermediate hole section. If any subsequent hole interval is deeper than the first, a full BOP test will be required.