

HOBBS OCD

AUG 20 2020

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-22226
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Jay Management Company, LLC		6. State Oil & Gas Lease No. OG-3846& K-5061
3. Address of Operator 1001 West Loop South, Suite 750 Houston, TX 77027		7. Lease Name or Unit Agreement Name SHELL STATE COM
4. Well Location Unit Letter H : 1980 feet from the North line and 660 feet from the East line Section 17 Township 11 S Range 33 E NMPM County Lea		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4305 KB		9. OGRID Number 247692
		10. Pool name or Wildcat NORTH BAGLEY

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

06/03/20 Attempt to pull tubing. Tubing stuck in the hole. Call OCD for instruction.

06/04/20 RIH w/ free point (Per Kerry w/ OCD). Tubing 100% free @ 5618'. Call OCD for instruction. Pump 75 sx class "H" cmt (Per Kerry w/ OCD). WOC.

06/05/20 Attempt to pressure test casing. Test fail call OCD for instuction. Pump 25 sx class "H" cmt (Per Kerry w/ OCD). WOC.

06/08/20 Pressure test casing to 500 psi. Test pass. Cut tubing @ 5600' (Per Kerry w/ OCD). Perf @ 5580'. Sqz w/ 50 sx class "C" cmt (Per Kerry w/ OCD). WOC.

06/09/20 Attempt to tag. No tag pressure test casing to 500 psi. Test pass. Call OCD for instruction. Spot balance plug @ 5580' w/ 25 sx class "C" cmt (Per Kerry w/ OCD).

Perf @ 3803'. Sqz w/ 40 sx cmt. WOC. Attemet to tag. No tag Call OCD for instruction.

06/10/20 Spot 25 sx cmt @ 3803' (Per Kerry w/ OCD). Perf @ 2407'. Sqz w/ 60 sx cmt. WOC. Tag plug @ 2303'. Perf @ 1707'. Sqz w/ 60 sx of cmt. WOC.

Tag plug @ 1575'. Perf @ 400'.

06/11/20 Circulate cement to surface. Cut off wellhead 4' below ground level. Verify cement to surface. Install dry hole marker.

Spud Date:

06/02/2020

Rig Release Date:

06/11/2020

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Analyst DATE 08/11/2020

Type or print name Nhi Le E-mail address: nle@jaymgt.com PHONE: 713-621-6785

For State Use Only

APPROVED BY: [Signature] TITLE CO DATE 8-20-20

Conditions of Approval (if any):