

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
HOBBS OGD

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
RECEIVED
AUG 25 2020

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-33427
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator Penioco Oil Corporation		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 2769, Hobbs, NM 88241-2769		7. Lease Name or Unit Agreement Name Kyk
4. Well Location Unit Letter I : 1980 feet from the SOUTH line and 600 feet from the West line Section 23 Township 20 S Range 38 E NMPM County Lea		8. Well Number 3
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3567'		9. OGRID Number 17213
		10. Pool name or Wildcat Abo, Blinberry, Tubbs

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐ **PNR**

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8.4.20 - 8.6.2020
MC BASU & P&A Strip. RU WISU. DH w/ rods/pump. Unset TAC. NU B O.P.
TDH w/ TBS. RU wireline. Set CIBP @ 5950'. TDH w/ TBS. One hole w/ 10" gelled brine.
Spotted 26' of Class C Cement. WOC 4 hrs. TDH tag TOC @ 5916'. Perforated 4 holes @ 2970'
TDH w/ TBS. Spotted holes w/ 35 SX Class C. WOC 4 hrs. Tagged TOC @ 2619'.
Perforated 4 holes @ 1700'. Spotted w/ 35 SX. WOC 4 hrs. Tagged @ 1347'. Perforated 4 holes @ 150.924/
DWC. 36 SUC. to surface. ND BOP. RD all equip.
Emitted 42 Steel PH. Will cut off wellhead. install DHM. Cleanup loc. within
90 days.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

Type or print name
For State Use Only

E-mail address:

PHONE:

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):