Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103	
Office District 1 – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 811 S. First St., Artesia, NM 882413 OIL CONSERVATION DIVISION District III - (505) 334-6430 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Azte, NM 87410 Santa Fe. NM 87505		WELL API NO.		
811 S. First St., Artesia, NM 882435 OIL CONSERVATION DIVISION		30-025- 06739 5. Indicate Type of Lease		
District III – (505) 334-6 20 1220 South St. Francis Dr.		STATE	FEE XZ	
District III - (505) 334-6430 1000 Rio Brazos Rd., Azte, NM 87410 2020 South St. Francis Dr. District IV - (505) 476-3460 100 Santa Fe, NM 87505		6. State Oil & Gas Lea		
1220 S. St. Francis Dr., Santa Falling 87505				
SUNDRY MOLICES AND REPORTS ON WELLS			7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			j	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Argo "A"	-
1. Type of Well: Oil Well Gas Well Other			8. Well Number 7	
2. Name of Operator			9. OGRID Number	
Apache Corporation			873 10. Pool name or Wildcat	
3. Address of Operator				
303 Veterans Airpark Lane, Ste. 3000, Midland, TX 79705 4. Well Location			Penrose Skelly, Graybu	urg & Paddock
" · · · · · · · ·				
Section 22 Township 21S Range 37E NMPM CountyLea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
	3421' GR	TAND, KI, OK, CIC.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBS			SEQUENT REPORT OF: K	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI				DA X
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT				ONR
DOWNHOLE COMMINGLE				r. C
CLOSED-LOOP SYSTEM	_			
OTHER: OTHER: OTHER: OTHER: OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
1. 08/07/20 Notified OCD of intent. Rig up P & A equipment				
2. 08/10/20 Set 5 1/2" CIBP @ 5250' circ mlf @ 5250'-2500' spot 25 sxs class c cmt from 5250' tag @ 5000' set 5 1/2" cibp @ 3776'				
spot 25 sxs class c cmt , , faq 8-12-20				
3. 08/11/20 Perf @ 2963' M & P 55 sxs class c cmt/tag toc @ 2734' perf @ 1150' M & P 55 sxs class c cmt tag @ 870' perf @ 276'				
circ 112 sxs class c cmt on 5 1/2" csg and 8 5/8" to surf JRD P & A equip. Back drag location. Cut off wellhead & remove Install dry hole marker (P & A complete. 8 1/3 1 20 method cmt @				
Cut off wellhead & remove. Install dry hole marker. P & A complete. 8 1/3/20 verified cont @ Surface.				
sugue.				
•				
		·	•	
		·	·	
Spud Date:	Rig Release Da	to.		
Spud Date.	Kig Kelease Da	ie.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
	,	, ,		•
arany (W/	' /) mymy n		Ď. 4 MŽ	,
SIGNATURE ()	TITLE	Agent	DATE	08/13/20
Type or print name Jimmy Bagley E-mail address: _sunsetwellservice@yahoo.com PHONE: 432-561-8600				
For State Use Only				
APPROVED BY: Say Fut TITLE () H DATE 8-27-20				
Conditions of Approval (if any):				
THE MODIZED BY QUIAN BUILS, SR. ROLLAMATION FOREMAN, APACKE CORP.				