Submit 3 Copies To Appropriate District State of New Mexico	
Office State of New Wexten	Form C-103
<u>District 1</u> Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	May 27, 2004 WELL API NO.
District II OIL CONSERVATION DIVISION	30-005-10501
District III  OIL CONSERVATION DIVISION  1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE  FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Cato San Andres
PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other	8. Well Number 17
1. Type of Well: Oil Well ☑ Gas Well ☐ Other  2. Name of Operator	9. OGRID Number
UHC New Mexico Corp.	183718
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 450, 303 W. Main, Ste. 300, Artesia, N.M. 88210	Cato San Andres
4. Well Location	
Unit Letter C: 660 feet from the North line and 1980	
Section 10 Township 8S Rugge 7 3 QE	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
Pit or Below-grade Tank Application □ or Closure □	
	ance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume Delow-Grade Tank: Volume	nstruction Material
12. Check Appropriate Box to Indicate Nature of Notice,	Depart on Other Date
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   COMMENCE DRILLING OPNS   PAND A	
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON CONTROL WOR	K ⊠ ALTERING CASING □
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN	ГЈОВ 📙
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At	tach wellbore diagram of proposed completion
or recompletion.	
04-07-06 MIRU. Ran pkr in 30', set. Load casing, cut 4 ½ off weld bell nipple, pulled pk	r out, put on new wellhead & BOP. Ran bailer
& tbg in, tag, shut dn.	
04-10-06 RIH w/ tbg, tag. Started bailing and clean out. POOH w/ tbg, dump fill. RIH w backside, pressure up to 300psi. Held ok. Unset pkr, POOH w/ tbg and took pkr off. RIH	
backside, pressure up to 300psi. Held ok. Oliset pki, FOOH w/ tog alid took pki off. Kiff	w/ production string & shut down.
04-11-06 RIH w/ pump & rods.( 110 3/4, 220 7/8, 2 x 1 1/2 x 10 pump, 106 jts 2 3/8, 2 3/8 s	SN, 4 perf subs., bull plug). Tag, set pump.
Test pump action. Rig down.	
I hereby certify that the information above is true and complete to the best of my knowledg	e and belief. I further certify that any pit or below-
grade tank has been will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.	
TITLES FIELD REFRESEN	
$\mathcal{L}(t) \nabla (t)   \mathbf{R} = \mathcal{L}(t) \nabla (t)   \mathbf{R}$	
	TATIVE II/STAFE ANA 05-18-06
	TATIVE II/STAFE ANA 05-18-06
	TATIVE II/STAFE ANA 05-18-06
	TATIVE II/STAFE MANAGER
Type or print name Regina Wolf E-mail address: regina@lothian.us To	TATIVE II/STAFE MANAGER