

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-20019
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Cato
8. Well Number 70
9. OGRID Number 183718
10. Pool name or Wildcat Cato San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator UHC New Mexico Corp.	
3. Address of Operator P.O. Box 450, 303 W. Main, Ste. 300, Artesia, N.M. 88210	
4. Well Location Unit Letter <u>D</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line Section <u>16</u> Township <u>8S</u> Range <u>30E</u> NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application ☐ or Closure ☐	
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____	
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☒ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ P AND A ☐ CASING/CEMENT JOB ☐ OTHER: ☐
--	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

04-03-06 RIH w/ drill bit collars & tbg, tag @ 670'. Started circulation, couldn't pass through. POOH, RIH w/ tbg, tag @ same spot. POOH, RIH w/ impressor block & tbg. POOH, took BOP & wellhead off. Dug wellhead out & shut down.

04-04-06 RIH w/ 4 1/2 spear, p/u 85000 tension, couldn't get casing out because casing was stuck. Casing was parted @ 511'. Took spear off, put on wellhead & BOP. RIH w/ taper mill w/ drill collars & tbg, tag @ 511', mill out. Go down 60', POOH, lay down tools, RIH w/ mule shoe jt, SN & tbg, tag @ 511'. Passed through to 1000', tag, circulate hole. Pulled tag up to 600' & shut down.

04-05-06 RIH w/ tbg to TD. Circulated, clean, pulled 5 jts out. Nipple down BOP, flanged well. RIH w/ pump & 75 rods. Closed well, shut down.

04-06-06 Finish running rods in, tag, spaced out, hang on, check p/a. Nipple up flow line, clean location & shut down.

04-07-06 Rig down.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Regina Wolf TITLE Production Clerk DATE 05-23-06

Type or print name Regina Wolf E-mail address: regina@lothian.us Telephone No. 505-746-4448

For State Use Only

APPROVED BY: Ray W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE May 30 2006

Conditions of Approval (if any):