Subrait 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office	Energy, Minerals and Natural Resources	May 27, 2004
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II	OIL CONSERVATION DIVISION	30-025-28270
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE ☐ FEE ☒
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Z	300215
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT LISE THIS FORM FOR PROPOSALS T	O DRILL OR TO DEEPEN OR PLUG BACK TO A	FALLI
DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)	N FOR FERIVITI (FORIVI C-101) FOR SOCIT	FeeKJ 8. Well Number 1
	Well Other	
2. Name of Operator		9. OGRID Number 227069
Momentum Energy Corporation		10. Pool name or Wildcat
3. Address of Operator P.O. Box 3398, Midland TX 79702		Scharb Queen
F.O. Box 3376, Wildiand 177 7702		
4. Well Location Unit Letter N :660feet from theSouth line and1980feet from theWestline		
D OCT NIMDM County I ea		
Section 3 Township 19S Range 35E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3888.9 GR		
Pit or Below-grade Tank Application or Closure		
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water		
• • • • • • • • • • • • • • • • • • • •		s; Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
TO THE ALTERNAC CACING		
	00,442,42,442	E DRILLING OPNS. P AND A
, 2 0	IANGE PLANS	
PULL OR ALTER CASING ML	DETIFIE COIVIFE LI CASING/CE	
OTHER:	OTHER:	
10 D 21 completed energions. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work) SFF RIII.E 1103. For Multiple Completions: Attach welloofe diagram of proposed completion		
or recompletion. We propose to P&A as follows: 1. Set CIBP @ 4550', cap with 20' cement, 150'. 2. Circulate casing with mud-laden fluid. 3. Set 20 sack cement plug @ 1850 - 1700'. — ALL PLUGS ARE Z55X OR 100'.		
We propose to P&A as follows:		
bumb sx if 400 TEO		
1. Set CIBP @ 4550', cap with 20' cement, 150'.		
1. Set CIBP @ 4550', cap with 20' cement, 150'. 2. Circulate casing with mud-laden fluid. 3. Set 20 sack cement plug @ 1850 - 1700'. 4. Set 20 sack cement plug @ 495-395'. 5. Set 10 sack cement plug 60' to surface. SHOCHTAG SHOE PLUG		
1 0 100 - 1		
5. Set 10 sack cement plug 60' to surface. 6. Install marker, clean location.		
6 Install marker clean location		
THE OIL CONSERVATION DIVISION MUSI		
BE NOTIFIED 21 LOURS PRIOR TO THE		
	REGINNING OF F	LUGGING OPERATIONS.
	Prainting of .	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.		
Right talk liss been will be done detect of close	, ,	
SIGNATURE June 1	TITLE Operation	
Type or print name Sammie L. Hodges E-mail address: shodges@momentumenergy.com Telephone No. 432/682-0595		
For State Use Only		
	Vank TITLE D REFRESEN	YATIVE II/STAFF MANACEDATE
APPROVED BY: (if any):	1.11.00	MAY 3 0 2006
Conditions of Approval (if affy):		LIM 8 . 1000