Form 3160-5		HOBBS	1
Form 3160-5 UNITED STATES (August 1999) DEPARTMENT OF THE INTERIOR		FORM APPROVED OMB No. 1004-0135	
BUREAU OF LAND MANAGEMENT			Expires November 30, 2000 5. Lease Scrial No.
SUNDRY NOTICES AND REPORTS ON WELLS			NM24166
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well			7. If Unit or CA/Agreement, Name and/or No.
🖾 Oil Well 🔲 Gas Well 💭 Other			8. Well Name and No.
2. Name of Operator			Sprinkle Federal #2
Lynx Petroleum Consultants, Inc. 3a. Address 3b. Phone No. (include area code)			9. API Well No. 30-025-28520
P.O.Box 1708 Hobbs, NM 88241 (505) 392-6950			10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Scharb-Bone Springs
660' FNL & 330' FEL			11. County or Parish, State
Sec. 9, T-19S, R35E			Lea County, NM
12. CHECK APPROFRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION			
	Acidize Deepe	n Droduction (Star	t/Resume) U Water Shut-Off
Notice of Intent		re Treat	
Subsequent Report	Casing Repair 🔲 New (Construction 🖸 Recomplete	Dandon Well Integrity
2		nd Abandon 🔲 Temporarily Al	vandon 2520
Final Abandonment Notice	Convert to Injection Plug H	-	
testing has been completed. I determined that the site is ready	inal Abandonment Notices shall be filed only for final inspection.) ng and abandonment: P.	surface locations and measured and tr nd No. on file with BLM/BLA. Requ a multiple completion or recompletion after all requirements, including recl gelled brine muc	iny proposed work and approximate duration thereof. ue vertical devits of all pertinent markers and zones. ired subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed price amation, have been completed, and the operator has
3. Spot 10 sxs. cement on top of CIBP 09465'.			APPROVED
 4. POOH with tbg. 5. RU wireline unit. Cut, pull, and LD 7900' 5 1/2' casing. 6. TIH with tubing to 7950'. 7. Spot 50 sxs. cement plug 7950' - 7750'. 8. Spot 50 sxs. cement plug 3580' - 3380'. 9. Spot 50 sxs. cement plug 1700' - 1500'. 10. Spot 50 sxs. cement plug 450' - 250'. Tag plug. 			
11. Spot 10 sxs. at surface.			
12. Cut off wellhead. Install dryhole marker.			
13. Cut off anchors. Clean up location.			
14. I hereby certify that the forego	ing is true and correct		
Name (Printed/Typed) Larry Scott,		Title President	
Harry Beote		Title President	
Signature Marrie		Date 3/23/06	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by Mis William OC DISTRICT SUPERVISOR/GENERAL MANAGER			
Conditions of approval, if any, a	e attached. Approval of this notice does not	Watrant or	JUN 1 5 2006
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, factitious or fraudulent statements or representations as to any matter within its jurisdiction.			

