

DISTRICT I
1625 French Drive Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.

30-025-33270

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-2148

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Caprock Maljamar Unit

1 Type of Well:

OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator

The Wiser Oil Company

8. Well No.

207

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico (505) 392-9797

9. Pool name or Wildcat

Maljamar Grayburg San Andres

4. Well Location

Unit Letter O : 1234 Feet From The South Line and 1404 Feet From The East Line

Section 19 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4087' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Return to production - downhole failure ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/03/03 MIRU Eunice Well Service. Stack out rods. ND WH. RU BOP. Tbg. stuck. Back rods off pump. POH w/rods. RU Rotary WL. Ran freepoint test. Tbg. free @ 4415'. Chemical cut tbg. @ 4325'. RD WL. Fish in hole: 1-1/2 jts. 2-3/8" tbg., SN, MSMA & 2" x 1-1/2" x 20' pump. POH w/131 jts. 2-7/8" tbg., 2-3/8" x 2-7/8" crossover & 11 1/2 jts. 2-3/8" tbg.

6/04/03 RIH w/overshot, jars & DC's to 4285'. Tag fish. Fish moved up hole 12' but would not release. Release off fish w/overshot. POH w/tbg. & tools.

6/05/03 RIH w/4-15/16" shoe, wash pipe, DC's on 2-7/8" tbg. to 4316' & tag. Mill to 4370'. POH w/tools & tbg. Cutrite shoe worn out.

6/06/03 RIH w/new shoe, wash pipe, DC's on 2-7/8" tbg. to 4370' & tag. Mill to 4380'. Circulate hole clean. POH w/tbg. & tools.

6/09/03 RIH w/4-3/4" overshot, grapple bumper sub, Johnson jars & DC's on 2-7/8" tbg. Caught fish @ 4287'. POH w/2-7/8" tbg. LD tools & fish. Fish was: 3-1/2 jts. 2-7/8" tbg., SN, MSMA & 1-1/2" x 20' pump w/1-1/4" x 6' GA. RIH w/2-7/8" tbg. Tbg. @ 4035'. SN @ 4000'. NU WH. RD BOP. RIH w/rods & 1-1/2" x 20' pump. Hung well on. Left pumping to CMU Battery "B".

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner
TYPE OR PRINT NAME Mary Jo Turner

TITLE Production Tech II DATE July 11, 2003
TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY Laurel White
CONDITIONS OF APPROVAL, IF ANY:

OC FIELD REPRESENTATIVE II/STAFF MANAGER

TITLE DATE JUL 31 2003