Form 3160-5 (August 1999)

Oil Cons. N.M. DIV-Dist. 2

UNITED STATES 1301 W. Grand Avenue DEPARTMENT OF THE INTERIARTESIA, NM 88210 BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					17444	
					If Indian, Allottee or Tribe Name If Unit or CA/Agreement, Name and/or No.	
SUBMIT IN TRIPLICATE - Other instructions on reverse side						
1. Type of Well ☐ Oil Well 🏻 Gas Well ☐ Other	2031-12,3			8. Well Name and No. FEDERAL COM "34" #1		
2. Name of Operator GREAT WESTERN DRILLING COMPANY		1 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			9. API Well No. 30-025-35998	
3a. Address P.O. BOX 1659 MIDLAND, TX 79702		3b. Phone No. (include treasede) (915)682-5241 Procedure (915)682-5241 Procedu			10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Descript. 1,700' FSL & 950' FEL SEC. 34, T-15-S, R-34-E		"I'ESIA S			11. County or Parish, State LEA COUNTY NM	
12. CHECK APPROPR	LIATE BOX(ES) TO IN	DICATE	NATURE	P NOTICE, R	EPORT, O	R OTHER DATA
TYPE OF SUBMISSION			TYPE OF ACTION			
Notice of Intent ☐ A Subsequent Report ☐ G	Alter Casing Casing Repair	Deepen Fracture Tre New Constr Plug and Ab	uction	Production (Star Reclamation Recomplete Temporarily Aba		□ Water Shut-Off□ Well Integrity□ Other
☐ Final Abandonment Notice ☐ ☐	Convert to Injection	Plug Back		Water Disposal		
testing has been completed. Final Abandonment Notices shall be filed only after all requirement determined that the site is ready for final inspection.) Perfs 12,706-12,716' tested water with no gas. Now plan to P&A. 1. □Set CIBP 12,650' & cap w/ 30 sx cmt 2. □Cut 5 ½" casing +/- 9,000' 3. □150' cmt plug in & out of 5 ½" stub - 80 sx 9075' to 8925' 4. □100' cmt plug in & out of 9 5/8" shoe at 6,210' - 80 sx 6,260-6,160' 5. □100' cmt plug across base of salt (2,790') - 40 sx - 2,725-2,825' 6. □100' cmt plug across top of salt (1,825') - 40 sx 1,825-1,925' 7. □100' across surface shoe depth (400') - 60 sx - 450' to 350' 8. □60' plug at surface - 25 sx. 9. □Cut & remove wellhead - weld on cap, reclaim location.				APP JUL GAR	ROVI	JUL 2003
14. I hereby certify that the foregoing is true and correct Norma (Printed(T)) and Title						Hobbs OCD
Name (Frintea) viea /			PETROLEUM ENGINEER			
Signature A Signature		Date 06/17/2003				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by			Title	Title Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.						

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on reverse)

(Instructions on reverse)

GWW