Submit 3 Copies To Appropriate District       State of New Me         Office       Energy, Minerals and Nature         District I       Energy, Minerals and Nature	
1625 N. French Dr., Hobbs, NM 88240District III301 W. Grand Ave., Artesia, NM 88210OIL CONSERVATIONDistrict III1000 Rio Brazos Rd., Aztec, NM 87410	WELL API NO.30-025-360735. Indicate Type of Lease
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	7505 STATE FEE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	the back me is a second traine of onthe Agreement Name:
1. Type of Well: Oil Well 🔀 Gas Well 🗍 Other	WTYSRU 924
2. Name of Operator Chesapeake Operating, Inc.	8. Well No. 924
3. Address of Operator P. O. Box 18496, Oklahoma City, OK 73154-0496	9 Pool name or Wildort
4. Well Location	
Unit Letter F : 2560 feet from the North	line and 2210 feet from the West line
Section         9         Township         20S         Range         33E         NMPM         Lea         County           10.         Elevation (Show whether DR, RKB, RT, GR, etc.)         Elevation (Show whether DR, RKB, RT, GR, etc.)	
GL: 3540' 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
PERFORM REMEDIAL WORK PLUG AND ABANDON	SUBSEQUENT REPORT OF: REMEDIAL WORK
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING C MULTIPLE C COMPLETION	CASING TEST AND CEMENT JOB
OTHER: Convert to water injection per order OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.	
<ol> <li>MIRU workover unit. POOH w/pump laying down rods. Pkck up add'l tbg &amp; tag PBTD @3262', circulate well clean as required. POOH laying down tubulars.</li> <li>RIH w/2-3/8" x 5-1/2" AD-1 pkr &amp; 2-3/8" duoline tubing. Set pkr @±2988', NU injection well head.</li> </ol>	
<ul> <li>3) Load annulus w/pkr fluid. Perform state witnessed MIT. RDMO workover unit.</li> <li>4) MIRU acid service company. Tie on to tbg &amp; bullhead 1000 gal 15% NEFe acid into zone. Over-displace w/50 bbl lease wtr.</li> <li>5) Put well on injection at 300 BWPD.</li> <li>Convert to injection per order #WFS-791</li> <li>Sundry Seart to BLM</li> </ul>	
Convert to injection per order #WFS-791	2 m 2003
Sundry Sent to BLM	The poper state of the poper sta
hereby certify that the information above is true and complete to the best of my knowledge and belief.	
	Asset Manager DATE 07/30/03
Ype or print name         Andrew J. McCalmont           This space for State use)         Notes	<b>Telephone No.(405)</b> 848-8000
APPPROVED BY <u>Law</u> Wink <u>OC</u> FIELD REPRESENTATIVE II/STAFF MANAGER Conditions of approval, if any:	
ч	