Submit 3 Copies To Appropriate District State of New Mexic	
Office Energy, Minerals and Natural	Resources March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-27432
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DI	VISION 50-023-27432 5. Indicate Type of Lease
District III 1220 South St. Francis	Dr. STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 8750	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	L-6309
87505	Z V V V V V V V V V V V V V V V V V V V
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BADIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SU	CH Central EK Queen Unit
PROPOSALS.)	8. Well Number
1. Type of Well:	001
Öil Well ☑ Gas Well ☐ Other Water Injection Well	
2. Name of Operator	9. OGRID Number
Seely Oil Company	020497
3. Address of Operator	10. Pool name or Wildcat EK Yates – Seven Rivers - Queen
815 W. 10 th St., Ft. Worth, TX 76102	EN Tales – Seven Rivers - Queen
4. Well Location Unit Letter M: 660 feet from the South line and 660 feet from	the West line
Section 9 Township 18S Range 34E NMPM Lea	
11. Elevation (Show whether DR, RR	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-14	must be attached)
Pit Location: UL Sect Twp Rng Pit type Depth	to GroundwaterDistance from nearest fresh water well
Distance from nearest surface waterBelow-grade Tank Location UL	
feet from theline andfeet from theline	
leet from thetime	
12. Check Appropriate Box to Indicate Natu	re of Notice, Report or Other Data SUBSEQUENT REPORT OF:
	· · · · · · · · · · · · · · · · · · ·
	EMEDIAL WORK ☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK PLUG AND ABANDON R	EMEDIAL WORK ☐ ALTERING CASING ☐ OMMENCE DRILLING OPNS.☐ PLUG AND ☑
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE C	EMEDIAL WORK ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C	OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER:	ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER: COMPLETION C 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple C	ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER:	ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER: COMPLETION C 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Cor recompletion.	ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER: COMPLETION C 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple C	ALTERING CASING DIMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER: COMPLETION C 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 5/23/06 - CIBP was set @ 4359'. 35' of cmt was dumped on top.	ALTERING CASING DIMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER: COMPLETION C 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Cor recompletion.	ALTERING CASING DIMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER: COMPLETION C 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 5/23/06 - CIBP was set @ 4359'. 35' of cmt was dumped on top.	ALTERING CASING DIMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER: COMPLETION C 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 5/23/06 - CIBP was set @ 4359'. 35' of cmt was dumped on top.	ALTERING CASING DIMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER: COMPLETION C 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 5/23/06 - CIBP was set @ 4359'. 35' of cmt was dumped on top. Waiting on a plugging crew.	ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMPLETION COMPL	ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion of my knowledge and belief. Further certify that anythor below-
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMPLETION COMPL	ALTERING CASING DIMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion of my knowledge and belief. Further certify that anythor below-
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMPLETION COMPL	ALTERING CASING DIMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Intent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion of my knowledge and belief. Further certify that anythor below-teneral permit or an (attached) alternative OCD apparator plan cutive Vice President DATE: 06/22/06
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING MULTIPLE COMPLETION C OTHER:	ALTERING CASING DAMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion of my knowledge and belief. Further certify that anythor below-teneral permit or an (attached) alternative OCD apparator plan cutive Vice President DATE: 06/22/06 Erson@seelyoil.com Telephone No.: 817-332-1377
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMPLETION CO	ALTERING CASING DAMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion of my knowledge and belief. Further certify that any of plan central permit or an (attached) after the completion of the control of
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMPLETION CO	ALTERING CASING DAMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion of my knowledge and belief. Further certify that anythor below-teneral permit or an (attached) alternative OCD apparator plan cutive Vice President DATE: 06/22/06 Erson@seelyoil.com Telephone No.: 817-332-1377