## N V MEXICO OIL CONSERVATION COMISSION

Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper igent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval with any inodifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan is approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of no		
NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO CHEMICALLY TREAT W	SHOOT OR ELL
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO OTHERWISE ALTER CAS	
NOTICE OF INTENTION TO REPAIR WELL		
NOTICE OF INTENTION TO DEEPEN WELL	NOTICE OF INTENTION TO	PLUG WELL
	Hobbs, New Mexico	August 9-7-41
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico	Place	Date
Gentlemen: Following is a notice of intention to do certain work as d	escribed below at the	
Stanolind Oil and Gas Company E. C. Hi Company or Operator Lease	11 "A" Well No. 37	in Lot 16
of Sec. 6 , T. 21-S , R. 37-E ,	N. M. P. M., He	erdy Field,
Lea County County.		
casing at 3517 with 225 sacks of cement.	-	
cesing at 3517 with 225 sacks of cement.  At this time we will test this shut-off by for 30 minutes. If test is okay, plug wil up and held for 30 minutes.	building up 1000# presson to be drilled and 1000# property	ure and holding
At 3:00 A. M., September 10th, 1941, 72 hocesing at 3517 with 225 sacks of cement.  At this time we will test this shut-off by for 30 minutes. If test is okay, plug will up and held for 30 minutes.  If test are okay, drilling will be resumed	building up 1000# presson to be drilled and 1000# property	ure and holding
cesing at 3517 with 225 sacks of cement.  At this time we will test this shut-off by for 30 minutes. If test is okay, plug wil up and held for 30 minutes.	building up 1000# presson to be drilled and 1000# property	ure and holding ressure again built