

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Arapahoe, NM 88210

DISTRICT III
1000 Rio Grande Rd., Aztec, NM 87410

WELL API NO.	30-025-09221
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	32447
7. Lease Name or Unit Agreement Name	SEVEN RIVERS QUEEN Unit
8. Well No.	56
9. Pool name or Wildcat	SEVEN RIVERS QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER <u>Injection</u>	2. Name of Operator <u>AREDA RESOURCES INC.</u>
3. Address of Operator <u>4920 S. LEWIS STE 107 TULSA OK. 74105</u>	4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>6600</u> Feet From The <u>EAST</u> Line Section <u>2</u> Township <u>23S</u> Range <u>36E</u> NMPM <u>LEN</u> Country _____
10. Elevation (Show whether DP, RKB, RT, CR, etc.) <u>3439 GL</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOBS ☐ Approved as to plugging of the Well Bore.
OTHER: ☐ Liability under bond is retained until ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

- (1) 4-18-06 MINN DBSL (NOTIFY NMOED)
- (2) 4-18-06 RTH w/ 2 3/8" WORKSTRING TO 3570' TAG EXISTING CIBP - CIRCULATE WELL w/ 9.54m
- (3) 4-18-06 Spot 35sx CLASS C CUT on Top of CIBP
- (4) 4-18-06 Spot 25sx CLASS C CUT @ 3000'
- (5) 4-19-06 Perforate @ 1350' - PRESSURE TO 2000' (HELD) - Spot 25sx CLASS C CUT @ 1400'
- (6) 4-19-06 Tag Plug @ 1400' TOC @ 1250'
- (7) 4-19-06 Perforate @ 375' - CIRCULATE CEMENT TO SURF. OF 2 3/8" 35 1/2" w/ 100SX CLASS C
- (8) 4-20-06 Cut-off well 3' Below Ground - Install DDM (RDM)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Corey Branton

TITLE

Plugging Supervisor

DATE

4-20-06

TYPE OR PRINT NAME

COREY BRANTON

TELEPHONE NO.

432 664 639

(This space for State Use)

APPROVED BY

Chris Williams

DISTRICT SUPERVISOR/GENERAL MANAGER

TITLE

DATE

JUL 05 2006

CONDITIONS OF APPROVAL, IF ANY: