Form 3160-5 (April 2004)

OCD-HOBBS

DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED					
OMB NO. 1004-0137					
Expires March 31, 2007					

5. Lease Serial No.

NM 04411

SUNDRY NOTICES AND REPORTS ON WELLS	L	NM 044	11	
Do not use this form for proposals to drill or to re-enter an	6.	If Indian,	Allottee or	Tribe Name
abandoned well. Use Form 3160-3 (APD) for such proposals.				

SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or C	CA/Agreement, Name and/or No.			
1. Type of Well		,, <u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>					
X Oil Well Gas Well Other				8. Well Name			
2. Name of Operator			West Lovington Strawn Unit				
Energen Resources Corporation				#3			
3a. Address	3b.	Phone No. (include are	ea code)	9. API Well N			
3300 N. A St., Bldg. 4, Ste. 100, M		(432) 684-3693	•	30 - 025 - 32	Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey L		(102) 001 0030			Strawn, West		
1880' FSL, 2080 FWL	• •			Lovingcon	JUICHII, NESC		
Sec. 33, T-15S, R-35E				11. County o	r Parish, State		
				Lea	NM		
12. CHECK APPROPRIATE	BOY(ES) TO INDICA	TE NATURE OF N	IOTICE DED				
	BOX(ES) TO INDICA	IE NATURE OF N	OTICE, REPO	JRI, UR UI	HER DATA		
TYPE OF SUBMISSION		TYP	E OF ACTION				
Notice of Intent	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamatio				
X Subsequent Report		Fracture 1 reat	Rectamatio	n	Well Integrity		
	Casing Repair	New Construction	Recomplete	e	X Other Add perfs		
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporaril	y Abandon			
	Convert to Injection	Plug Back	Water Disp	osal			
following completion of the involved operations. If testing has been completed. Final Abandonment N determined that the final site is ready for final inspec 8/9-9/8/2005 MIRUSU. Pumped 100 bbls produced correlation log. Perforate Strawn 11,580-94', 11,560-70', 11,516-34' 11,560-11,614' w/5000 gals 15% acrproduced water. RIH w/RBP reset a 2@ KCLW. Rig up Schlumberger. Actest to test tank. Run BH bomb w/w/100 bbls of produced water. RIH to battery.	water down tbg. None water down tbg. None water down tbg. None water down tbg. None was not was at 11,598-11,606'. It was not	D X-mas tree. W/4 SPF 60 deg Shot 200 holes Swab test to p & set packer -11.534' w/2000 0', 9000', 10,0 9', bottom of t	Rig up Bake ree phased v . RDWL Ac test tank. at 11,474'. gals 15%/a 00', 11 274 ubing @ 11,	r Atlas. w/stim gun idize Stra Kill well Loaded a cid w/150) ', 11,474' 520'. Swal	Run GR/CCL sleeves at wn perfs w/130 bbls nnulus w/140 bbls bio balls CSwab . Kill well b test. Put well		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	4	Title 6					
Garolyn Larson	/24	Regu k at	/ ory Analyst				
Carolin Laise	2	08 81 72 35-06					
	SPACE FOR FEDERA		ICE USE				
Approved by		Title	./	Da	nte		
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to twhich would entitle the applicant to conduct operations the	those rights in the subject le-	05 00	K				
The state of the s							