Office Office	State of New M		Form C-103
District I	Energy, Minerals and Nat	tural Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30 · 025 - 035 284	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
vistrict III 1220 South St. Francis Dr.		STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410  District IV  Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fc, NM		B-15B	
87505	CE AND REPORTS ON WELL	С	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			N. M. BZ 5+4+c
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			NCT 5
PROPOSALS.)  1. Type of Well:			8. Well Number
Oil Well X . Gas Well Other			4
<b>y</b>			9. OGRID Number
2. Name of Operator			9. OGRID Number
Pronghorn Mgt. Corp.  3. Address of Operator			10. Pool name or Wildcat
P.O. Box 1772 Hobbs N.M. 88241		SAN Simus Vates North (Assoc)	
4. Well Location	70.11. 000		The state of the s
Unit Letter F ::	<u> </u>	$\frac{1}{6}$ line and $\frac{1}{9}$	180 feet from the West line
2.8			,
Section 29	Township 2/5 I	Range 35 E	NMPM LEA County
	11. Elevation (Show whether D	R, RKB, RT, GR, etc.,	
Pit or Below-grade Tank Application (For p	it or helow grade tank electrons a fee	= C 144 must be steeple	2)
			Distance from nearest fresh water well
Distance from nearest surface water		SectTwp	Rng;
feet from theline and	feet from theline .		
PERFORM REMEDIAL WORK 🔀   TEMPORARILY ABANDON	PLUG AND ABANDON  CHANGE PLANS	SUB: REMEDIAL WORI	SEQUENT REPORT OF:
	MULTIPLE [] COMPLETION ·	CASING TEST AN CEMENT JOB	ADANDONMENT
OTHER:		OTHER:	
13. Describe proposed or complete	ed operations. (Clearly state all	Dertinent details and	give pertinent dates, including estimated date
of starting any proposed work)	SEE RULE 1103. For Multir	ole Completions: Att	give pertinent dates, including estimated date ach wellbore diagram of proposed completion.
			/ C// proposeg completion
1. Move in and Rig	Up. INSTALL B.O.	. <b>r</b> .	INL rolls
2. POOH with pro	duction equipm	ent,	Received
2. POOH with pro 3. Clean out we	-11 to total de	epth.	Hobbs -
4. Acidize existi	ng peatorutions	r.	· \sigma_s OCD \sigma_s
5. Return well	to production	,	10
nereby certify that the information abo	we is true and complete to the b		and belief. I further certify that Sity pos or below-
Imus. 1	B B-rerume's f	→ a Berrer ar her mit □ 0	and belief. I further certify that sit belower an (attached) alternative OCD-approved plan
IGNATURE MANUEL	·	PARTNEW	DATE 06/23/06
ype or print name G. A. BAh e	E-mail ad	ldress:	Telephone No. 392 - 249
This space for State use)	1		
PPPROVED BY Aug W.	Wand TITLE		TO THE MANAGED
onditions of approval, if any	TITLE FILL	ELD REPRESENTAT	TIVE ILISTAFF MANAGER JUL 1 0 2006