| Submit 3 Copies To Appropriate District | trict State of New Mexico | | | | Form C-103 |
|--|--|---------|---------------------------|-------------------------|------------------------|
| Office District I | Energy, Minerals and Natural Resources | | | | Revised March 25, 1999 |
| 1625 N. French Dr., Hobbs, NM 88240 District II | | | | WELL API NO. 30-025. | 21401 |
| 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr. | | | 5. Indicate Type | | |
| 1000 Rio Brazos Rd., Aztec, NM 87410 | | | STATE | | |
| 1220 S. St. Francis Dr., Santa Fe, NM | | | | 6. State Oil & 0 | ias Lease No. |
| SUNDRY NOTICES AND REPORTS ON WELLS | | | | 7 Lease Name o | r Unit Agreement Name: |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | | | J. F. B. | |
| 1. Type of Well: | | | | | |
| Oil Well Gas Well Other 2. Name of Operator | | | | 8. Well No. | |
| Pronghouw Mgt, Corp. 3. Address of Operator | | | | 6. Wen 146. | |
| 3. Address of Operator | | | | 9. Pool name or Wildcat | |
| P. D. Box 1772 Hobbs, N. M. 88240 505-392-2495 L. Well Location | | | | LANGIE MUST | Bueen |
| | | | | | |
| Unit Letter K: 1980 feet from the F5L line and 1030 feet from the FWL line | | | | | |
| Section 2/ Township Z45 Range 37 E NMPM Leu4 County | | | | | |
| 10. Elevation (Show whether DR, RKB, RT, GR, etc.) | | | | | |
| 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | | | | |
| NOTICE OF IN | | 1 | = | SÉQUENT RE | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | | REMEDIAL WORK | | ALTERING CASING |
| TEMPORARILY ABANDON | CHANGE PLANS | | COMMENCE DRIL | LING OPNS. | PLUG AND ABANDONMENT |
| PULL OR ALTER CASING | MULTIPLE COMPLETION | | CASING TEST AN CEMENT JOB | iD 🗆 | |
| OTHER: | | | OTHER: | | |
| 2. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. | | | | | |
| 1. Move in And Rig up. Install B.O.P. | | | | | |
| 2. Perforate Jalmut Yates zone. Stimulate as Necessary | | | | | |
| 3. Return well to production. | | | | | |
| | | | | 12 P | Received Hobbs OCD |
| | | | | 130 | 100 V32426250 |
| hereby certify that the information above is true and complete to the best of my knowledge and belief. | | | | | |
| 1 march | - | | _ | | DATE OI lastor |
| GIGNATURE ///////// | 1 | IILE TA | ent wen | <u> </u> | DATE 06/21/06 |
| Type or print name G.A.BA | ben | | | Telepl | none No. 392-2495 |
| This space for State use) | 1 | | | | , "T |
| APPPROVED BY Law 1 | wink t | HELD | REFRESENTATIVE | 7 dd 1440. | DATE |
| Conditions of approval, if any: | | | TATIVE | MISTAFF MANIA | GER JUL 1 () 2006 |