	a.			
Submit 3 Copies To Appropriate District	State of New Me	xico		Form C-103
Office	Energy, Minerals and Natural Resources		-	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-3 5. Indicate Type of I	
District III	1220 South St. Francis Dr.		STATE	FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas I	Lease No.
SUNDRY NOTICES	S AND REPORTS ON WEL	LS	7. Lease Name or U	nit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)	ALS TO DRILL OR TO DEEPEN O	OR PLUG BACK TO A	Simms 35 State	
1. Type of Well:			8. Well Number	
Oil Well 🗌 Gas Well 🕱	Other	RECEIVER	#4	
2. Name of Operator		JUN 2 2 2003	-9. OGRID Number	
Nearburg Producing Company		1008 -	456 01574	
3. Address of Operator	0 M 41 and my 70705	DU TEOIN	10. Poorname or W	
3300 N A St., Bldg 2, Ste 12 4. Well Location	0, Midland, 1X /9/05	18 21	// 1	West
		19 ⁶ 78	C1650 feat from	
Unit Letter <u>C</u> : 9	90 feet from the Nor	$\frac{1}{2}$ th $\frac{1}{2}$ in $\frac{1}{2}$	from feet from	the West line
Section 35	Township 20S	Range $\sqrt{0.35E}^{-6/4}$	NMPM N/	County Lea
	1. Elevation <i>(Show whether)</i>	DR, RKB, RIF, GR, et	<u> </u>	
Pit or Below-grade Tank Application or Closure				
Pit type Depth to Groundwater		water well Dis	tance from nearest surfac	e water
Pit Liner Thickness: mil	Below-Grade Tank: Volume_			
	//			_
	propriate Box to Indicate		± ·	
NOTICE OF INTEN			SEQUENT REPO	
	PLUG AND ABANDON 🗌	REMEDIAL WORK		
	CHANGE PLANS	COMMENCE DRILLI	NG OPNS. 🔲	PLUG AND
		CASING TEST AND		ABANDONMENT
		CEMENT JOB		
OTHER:		OTHER: TA and ch	uart	X
13. Describe proposed or completed op	perations (Clearly state all per			ding estimated date
of starting any proposed work). SI				
or recompletion.	•		5 1	
		· · · · · · · · · · · · · · · · · · ·		
NPC TA'd the subject well or NPC rep, and he was told to		—	ep. Call was made	e by Bill Young,
			1 1	••
See attached work breakdown	and chart	Approval of Ter ndonment Expla	nporary 17	1)
	l nis	Approvation num	0	
2	AOa		· · · · · · · · · · · · · · · · · · ·	
$\left(\right) $				•
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan				
SIGNATURE		LE Productio		DATE <u>6/21/06</u>
Type or print name Sarah Jordan	E-n	nail address:	sjordan@nearburg. Teleph	com one No. 432/686-8235
APPROVED BY Hay W. Winks OF THE ENTATIVE WATANT MARKER				
APPROVED BY_ Flary U). Why by define	, REPRESENTATIVE !	1/STAFF MANACEX	
			177	

Conditions of Approval, if any:

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Simms 35 State #4

990' FNL and 1650' FWL, Section 35-20S-35E Morrow Lea County, New Mexico ** ALL COSTS ARE FIELD ESTIMATES **

06/02/06 Well Repair Purpose: TA Well.

Road rig & crew to location from Grama Ridge East 34 State #1. MIRU Mesa Well
Service pulling unit. Well was shut in. Had 1250# tbg pressure on well. Blew dn tbg
pressure to atmosphere in 15-20 minutes. Blew dn csg pressure to frac tank catching 20
Bbls fluid. ND WH & NU BOP. Had Two-State set pipe racks & (1) 500 Bbl frac tank.
Tried to release pkr, but needed to load tbg before pkr would release. Had Lucky reverse
pump load tbg w/ 25 Bbls 2% KCL wtr. Was then able to release PLS pkr. Let well
equalize pressures to frac tank. POOH & LD 2 jts- 2 3/8" P110 4.7# EUE 8rd tbg, 2 3/8" x
4 1/2" XL On/Off tool w/ Baker 1.81""F" profile nipple, 2 3/8" x 4 1/2" 13.5# PLS 10k
pkr w/ 45k shear, 2 3/8" x 4' N-80 tbg sub w/ WLEG. Close BOP blinds. SDFW. Will
RIH w/ JB/GR first thing Monday AM before RIH & setting CIBP over perfs & dumping 35' cmt.

Current Operation This AM: RIH w/ JB/ GR to PBTD.

06/05/06 Well Repair Purpose: TA Well.

MIRU JSI electric line truck. Open BOP blinds. RIH w/ JB/ 3.625" Gauge ring/CCL to 13120'. Had no obstructions to keep from running CIBP on WL. POOH w/ Gauge ring. FL found @ 1260' FS. RIH w/ 3.50" Alpha CIBP/CCL & set@ 13,080' correlating w/ csg collar log JSI brought w/ them (which was previously correlated to Schlumberger's log). RIH w/ cmt dump bailer making 2 runs to put 35' cmt on top of CIBP. TOC @ 13,045'. RDMO JSI electric line truck. RIH w/ 399 jts- 2 3/8" P110 4.7# EUE 8rd tbg (open ended) to 12,957'. Put TIW valve in tbg. Close BOP rams. SDFN. Will load & test csg w/ 2% KCL wtr in the AM & circ pkr fluid before POOH & LD tbg on pipe racks.

Current Operation This AM: Test csg and CIBP.

06/06/06 Well Repair Purpose: TA Well.

Had Lucky reverse pump load csg w/ 25 Bbls 2% KCL wtr. Pressure test csg to 500#. Held good pressure. Bleed off pressure to frac tank. Start reverse circulating 520 Bbls 2% KCL wtr w/ double inhibited pkr fluid @ 1 3/4 bpm dn csg& out tbg to frac tank. Had vac trucks haul dirty wtr in frac tank to disposal. POOH & LD 399 jts- 2 3/8" P110 4.7#EUE 8rd tbg on pipe racks. ND BOP & NU new (3000#) B1 bonnet flange w/ 2" ball valve. Had Lucky reverse pump load csg w/ pkr fluid. Shut well in. SDFN. Will pressure csg w/ chart recorder for OCD in the AM.

Current Operation This AM: Pressure Test csg.

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Simms 35 State #4

990' FNL and 1650' FWL, Section 35-20S-35E Morrow Lea County, New Mexico ** ALL COSTS ARE FIELD ESTIMATES **

06/07/06 Well Repair Purpose: TA'd Well.

Had Lucky reverse pump top off csg w/ 2% KCL wtr & pkr fluid. Put chart recorder in line to record csg pressure. Pressure test csg to start pressure @ 620# for 40 minutes & finish pressure @ 600#. Made an acceptable chart. Did not have an OCD witness. Talked to Buddy Hill w/ OCD & he said to go ahead & test without him. Bled dn csg pressure. Removed chart from recorder. RDMO Mesa Well Service pulling unit & Lucky reverse pump. Will send chart in to Midland office to be filed w/ C-103 @ OCD office. Had Two-State load 401 jts- 2 3/8" P110 4.7# EUE 8rd tbg from pipe racks & take to Artesia yard. Release all other equipment. FINAL REPORT. Current Operation This AM: Well TA'd.

