

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-05114</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Denton North Wolfcamp</b> <b>Agree #8910087370</b>
8. Well Number <b>Tract 19, Well #9</b>
9. OGRID Number <b>019958</b>
10. Pool name or Wildcat <b>Denton Wolfcamp</b>

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
**3814 GR**

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type STEEL Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-7-06 Notify NMOCD, Gary Wrk  
6-8-06 Tag T.O.C. @6,757'. Circulate M.L.F.  
6-12-06 Cut & pull 7" from 4,840' w/jet cutter.  
6-13-06 Spot 75 sx. cmt. @4,890.  
6-14-06 Tag T.O.C. @4,693'. Spot 40 sx. cmt. - 3,050'-2,933'. Spot 40 sx. cmt. - 2,250'-2,129'.  
6-15-06 Mix & circulate 300 sx. cmt. down 9 5/8" csg. Thru perfs @353' with cement. Circulated to surface out 9 5/8" X 13 3/8" csg. Leave all of casing full of cement. Cut W.H. & Anchors. Install P & A Marker. Backfill cellar.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Randall Minear TITLE **P & A SUPERVISOR**

DATE: 6-23-06

Type or print name **RANDALL MINEAR**  
For State Use Only

Telephone No. 432-530-0907

APPROVED BY: Larry W. Wink  
Conditions of Approval (if any):

OC FIELD REPRESENTATIVE II/STAFF MANAGER  
TITLE

DATE **JUL 11 2006**