

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-34097
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	STATE 'AN'
8. Well No.	11
9. Pool Name or Wildcat	VACUUM ABO REEF

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITS (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>B</u> : <u>900</u> Feet From The <u>NORTH</u> Line and <u>1440</u> Feet From The <u>EAST</u> Line Section <u>7</u> Township <u>18-S</u> Range <u>35-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc)	3969'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: SET CIBP TO ELIMINATE WTR/REP CHANNEL ☒	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-05-06: MIRU. INSTALL PR & STUFFING BOX. 6-06-06: WORK ON RIG.
6-07-06: REL TAC. TIH W/TBG & BHA TO 3400. 6-08-06: TIH W/TBG BHA & TAG CIBP @ 8540. PUMP 220 BBLS 2% KCL.
6-09-06: CIRC GOOD RETURNS. DRILL @ 8540. FELL THRU TO 8562 ON CIBP.
6-12-06: START FOAM AIR FOR CIRC. SET DN @ 8560. NO HOLE. SET DN ON CIBP. TIH W/KILL STRING.
6-13-06: TIH & TAG @ 8565. DRILL 8565-8579. PULL TBG ABOVE PERFS.
6-14-06: TIH W/TBG. TAG @ 8578. C/O TO 8580. STUCK WORK TBG COME FREE. TIH & TAG @ 8578. WRK DN TO 8580. PULL 100 STANDS TBG.
6-15-06: PU NEW SHOE. TIH W/WP, JARC, DC'S. RUT EOT @ 6540. RU FOAM RIG. LOAD HOLE. TIH W/TBG & TAG @ 8579. DRILL FR 8579-8582.
6-16-06: TIH W/TBG. TAG @ 8582. DRILL. MADE 6". CIRC HOLE. KILL TBG. TIH W/KILL STRING. TIH W/NEW SHOE.
6-19-06: TIH W/TBG @ 6500. RU FOAM RIG. TIH W/TBG. TAG @ 8586. DRILL 8584-8586. PULL 29 STANDS EOT @ 6541.
6-20-06: TIH W/TBG. TAG @ 8685. C/O TO 8586. LOST 1'. TAG @ 8585. WRK DN TO 8586. PU 8' ON STRING. SET DN @ 8581. PU OVERSHOT W/GRAPPLE. TIH W/DC'S, BS, JARS, & TBG. EOT @ 6500'.
6-21-06: TIH W/TBG. TAG @ 8583. PUMP 50 BBLS 2% KCL DN TBG. TIH W/BHA & TBG. TAG UP & WORK W/FISH. LATCH ON. PULL 4 PTS OVER.
6-22-06: TIH W/JARS, DC'S & TBG. TAG ON FISH @ 8624. CONTINUE IN HOLE. TAG @ 8773. TAG @ 9571'. HIT DN ON FISH. JAR DN. TIH W/KILL STRING.
6-23-06: PU PKR & SET @ 8580. RU REV PUMP ON TBG. PUMP 2% KCL DN TBG. BLOW ON BACKSIDE. REL PKR. TIH W/KILL STRING.
6-26-06: TIH W/DC'S, BS, JARS, TBG. TAG @ 9571. LATCH ONTO FISH. FISH HUNG UP @ 9441. WORK FREE. TIH W/KILL STRING.
6-27-06: TIH W/90 STANDS TBG, 5541. TIH W/RODS.
6-28-06: RUN CSG INSPECTION LOG. TIH & TAG @ 9480. RUN LOG FR 9480-3500. TIH W/2 7/8" TBG.
6-29-06: TIH W/190 JTS WS. LD 100 JTS 2 7/8" TBG.
6-30-06: TIH W/RODS. TIH W/20 STANDS KILL STRING. 7-03-06: MIRU PUMP. 7-05-06: TIH W/TBG TO 6200'. 7-06-06: RIG DOWN.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist DATE 7/11/2006
TYPE OR PRINT NAME Denise Pinkerton Telephone No. 432-687-7375

(This space for State Use)

APPROVED DeWayne Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JUL 14 2006
CONDITIONS OF APPROVAL, IF ANY: _____