Form 3160-5 (September 2001)

## UNITED STATES DEPARTMENT OF THE INTERIOR DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT MODES, NEW 83240

OMB No. 1004-0135

Expires January 31, 2004

5. Lease Serial No.

## SUNDRY NOTICES AND REPORTS ON WELLS

LC-060978

SUNDRY NUTICES AND REPORTS ON WELLS				DC-000770
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well				Milnesand Unit
Oil Well Gas Well Other				8. Well Name and No.
				MSU #211
2. Name of Operator  Thompson, J. Cleo				9. API Well No.
3a. Address 3b. Phone No. (include area code)				30-041-10154
P. O. Box 12577, Odessa, TX 79768-2577 432-550-8887				10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  Unit Letter O, 330' FSL & 2310' FWL				Milnesand (San Andres)
Unit Letter O, 330' FSL & 2310' FWL				11. County or Parish, State
Sec. 20, T-8-S, R-35-E				Danasa Maria
12 CHECK AD	DDODDIATE DOVEC	TO DIDICATE ALA	<u>, D</u>	Roosevelt, New Mexico ORT, OR OTHER DATA
	PROPRIATE BUX(ES			ORI, OR OTHER DATA
TYPE OF SUBMISSION			ZZYPE OF ACTION	
	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	Reclamantion	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	
	Convert to Injection	Plug Back	Water Disposal	
6/9/06 Tagged plug @ 4116 6/12/06 WIH w/ tbg. tagged 6/13/06 Perf 4 1/2 csg. @ 2' WOC 4 hrs. Tagged plug @ 6/14/06 Perf. 4 1/2 csg. @ 2' psi. WOC 4 hrs. Tagged plug	U, cleaned out well to oo' on wireline. RIF 'POH w/ plugged to plug @ 4116'. Spot 750. Set packer @ 20, 2637' POOh w/ pa 250'. Set Packer @ 11g @ 2142' POH CV ot packer @ 30 ft. Br	I w/tbg. tagged plubg. 20 sx cmt POH w/ 437'. Establish ratecker CWI SDFN. 1944'. Establish ratevI SDFN. VI SDFN.	7 60 jts. WOC 4 hrs. Ta e of 1BPM @ 1500 psi. te of 1 BPM. @ 1400 p D BOP. NUWH, Circ.	cement on top POH w/ 60 jts. WOC agged plug @ 3792'. POH SDFN . Sqz. 50 sx cmt. CWI w/ 1200 psi. si. SQZ. 80 sx cmt. SWI w/ 1200 160 sx cmt. down 4 1/2 csg. and up ry Hole Marker.
14. I hereby certify that the foregoing is Name (Printed Typed)  Signature	P. Hugles Higher	Title Date	Forescer 6-22-06	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by Conditions of approval, if any, are attached		~	THE ELM ENGIN	Date JUL 1 0 2006

GWW

applicant to conduct operations thereon.