Submit 3 Copies To Appropriate District Office District 1	State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION		Form C-103 May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210			30-025-37015
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	0 Rio Brazos Rd., Aztec, NM 87410 <u>trict IV</u> 0 S. St. Francis Dr., Santa Fe, NM		STATE FEE X
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Bourdon 18
1. Type of Well: Oil Well X Gas Well Other		8. Well Number 005	
2. Name of Operator Chesapeake Operating Inc.			9. OGRID Number 147179
3. Address of Operator P.O. Box 11050			10. Pool name or Wildcat
Midland, T	X 79702-8050		D-K; Abo
4. Well Location		········	
· · · · · · · · · · · · · · · · · · ·	980feet from theNorth	line and660	feet from the East line
Section 18 Township 20S Range 39E NMPM CountyLea			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)3547 GR			
Pit or Below-grade Tank Application 🗋 or Closure 🗌			
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUE PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN			LLING OPNS. P AND A
OTHER:Plug Abo zone	X	OTHER:	Г
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 			
Chesapeake, respectfully, request permission to plug Abo zone per the attached procedure.			

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines \Box , a general permit \Box or an (attached) alternative OCD-approved plan [X].

TITLE

SIGNATURE

TITLE Regulatory Assistant

E-mail address:sstricklin@chkenergy.com

PETROLEUM ENGINEER

DATE 06/16/2006

DATE JUL 1 7 2006

Type or print name Shay Stricklin For State Use Only

Telephone No. (432)687-2992

APPROVED BY: Conditions of Approval (if any):

Bourdon 18-5 Lea County, New Mexico Plug Off Abo Procedure

Date: June 5, 2006

Location: 18H-T20S-R39E

Production Casing: 5 1/2" 17# L-80 LT&C 0-7586', ID-4.892", Drift-4.767", Burst-7,740#

PBTD/TD: 7,225[?]/7,600'

Current Perfs: Blinebry 6044-68' Tubb 6701-03', 6707-16', 6721-31', 6736-40', 6774-90', 6796-6805', 6808-10', 6828-34', 6840-42', 6848-53', 6872-78' Abo 7336-38', 7487-7514'

Recommended Procedure:

- 1. MIRU pulling unit. POH w/ rods, pump & tubing.
- 2. RU Wireline Co. Set CIBP @ 7300'. Dump 2 sxs of cement on top of the CIBP. RDMO Wireline Co.
- 3. RIH production tubing w/ TAC. Set SN on tubing below 6,900'. RIH w/ rods and 1.25" pump. Shorten the rod string by removing the 7/8" rods on top.

4. RDMO pulling unit.

1

5. Shorten the stroke length on the pumping unit to the shortest hole, slow the pumping unit down as slow as possible.