

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-07690
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit
Well No. 108
Pool name or Wildcat Hobbs (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> TA'D	
Name of Operator Occidental Permian, LTD	
Address of Operator 1017 W Stanolind RD. Hobbs, New Mexico	
Well Location Unit Letter <u>K</u> : <u>2310</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>15</u> Township <u>19-S</u> Range <u>38-E</u> NMPM <u>Lea</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.)	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-29-03 Tag Existing CIBP @ 4000' Circ. well w/ M.L.F. Spot 25 sks of cement 4000'-3622'
5-30-03 Perf @ 2680' Squeezed 50 sks of cement under a packer @ 1500 psi. Tagged @ 2370'
6-2-03 Perf @ 1600' Squeezed 35 sks of cement under a packer @ 1000 psi. Tagged @ 1370'
6-3-03 Perf @ 460' No circulation up annulus to surface. Squeezed 130 sks of cement. Tagged @ 77' Fill up 4 1/2 casing w/ 15 sks cement

Cut off wellhead and anchors 3' BGL. Cap well. Install dry hole marker. Clean location.

Approved as to plugging of the Well Bore
Liability under bond is retained until
surface restoration is completed.

APPROVED
AUG 2003
Hobbs
OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert Gilbert TITLE SR. Engr Tech DATE 6-5-03
TYPE OR PRINT NAME Robert Gilbert TELEPHONE NO. 397-8206

(This space for State Use)

APPROVED BY Gary W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE AUG 07 2003
CONDITIONS OF APPROVAL, IF ANY: