

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 87240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

May 27, 2004

WELL API NO.

30-025-37349

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

State "A"

8. Well Number

11-Y

9. OGRID Number

192463

10. Pool name or Wildcat

Hobbs: Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

OXY USA WTP Limited Partnership

3. Address of Operator

P.O. Box 4294, Houston, TX 77210-4294

4. Well Location

SHL: Unit Letter J : 1484 feet from the South line and 1526 feet from the East line
BHL: J 1903 South 1914 East
Section 29 Township 18-S Range 38-E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3647' GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: Open additional pay in the Wolfcamp ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Mark Stephens

TITLE Regulatory Compliance Analyst DATE 7/17/06

Type or print name Mark Stephens

E-mail address: Mark_Stephens@oxy.com

Telephone No. (713) 366-5158

For State Use Only

OC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY Hayden Wink

TITLE _____ DATE _____

Conditions of Approval, if any

JUL 24 2006

Open additional pay in the Wolfcamp as per the following procedure:

- 1) MI x RU. NU BOP x pull production equipment.
- 2) RIH with 4-3/4" bit x scraper and clean out to PBD (7830'). Circulate well clean.
- 3) RU wireline and perf at the following intervals -
7628'-34', 7649'-52', 7655'-57', 7659'-65', 7681'-82', 7693'-94', 7700'-04', 7719'-26',
7733'-34', 7738'-45', 7750'-52', 7759'-63', 7765'-68', 7774'-82', 7791'-98', 7800'-13'
(2 JSPF, 180 deg. phasing).
- 4) Acidize perfs with 4700 gal. 15% HCL.
- 5) Swab or flow back spent acid x circulate clean.
- 6) RBIH with production equipment.
- 7) ND BOP and RD x MO. Test well and return to production.