STATE OF NEW MEXICO


Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Submit 3 Copies to Appropriate District Office

OIL CONSERVATION DIVISION

DISTRICT I		40 Pacheco S		M	ELL API N	C 00 00'	- 07007	l
.O. Box 1980, Hobbs, NM 88240 Santa Fe, NM 87505			F	Indicate	30-025 Type of Lea	5-07287		
DIOTRICT !!				ြ		• •		
DISTRICT II P.O. Drawer DD, Artesia, NM 88821	0			6	STATE State Oil	≂ L	FEE	: <u> </u>
7.0. Diawer DD, 7110314, 7111 00021					. 01010 011	W 000 E00		
DISTRICT III								
1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS								
(DO NOT USE THIS FOR					Lease Nam	ne or Unit Ag	reement Nan	ne
	RESERVOIR. USE "API			BACKTOA				
	FORM C-101) FOR SUC	H PROPOSALS)			Knowles	s SWD	İ
1. Type of Well:	GA.	, _	7			7627	23	į
WELL	WE	1	ОТН	I ER	/0	200		
2. Name of Operator	Paladin Energ	v Corp		8	Well No.	> 00	na «	
2 Address of Operator		, y OO, p.			Pool hor		02 8	
3. Address of Operator 10290 Monroe Drive, Suite 301, Dallas, TX 75229					9. Pool name or Wildcat			
4 Well Location					- 1 '		100 CD	
					\\ \\ \\ \\ \\ \	. Se.	1. C.B.	
Unit Letter P	: <u>660</u> Fee	t From Th Sou	ıth Line	and 660	Feet from	m The	East	Liné
					1.	8/00	rererry	>
Section 3	4 Tov	vnship 165		ge 38E	NMPM	Le	a ELO	County
	Ele	vation (Sh	ow whether DF	,RKB, RT, GR, etc)				
		D 4 - 1	Pasta Natara	6 N - 4' D	4 - 0			
	eck Appropriate	Box to inc	licate Natur	•	-			_
	INTENTION TO:			SU	JBSEQU	IEM) RE	PORT O	F:
	1 4/1			3				
PERFORM REMEDIAL WORK		IG AND ABAND	ON	REMEDIAL WORK			TRG CSG	
TEMPORARILY ABANDON		IG AND ABAND ANGE PLANS	ON	COMMENCE DRLG		AL P8		
TEMPORARILY ABANDON PULL OR ALTER CASING			ON	CSG TST & CMT				
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	СНИ	ANGE PLANS		COMMENCE DRLG CSG TST & CMT	JOB	P8	kA	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Company of the Company	CHA	ANGE PLANS		COMMENCE DRLG CSG TST & CMT	JOB	P8	kA	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Comparing the Comparing any proposed or Comparing any proposed and proposed and proposed any proposed and proposed any proposed	CHA	ANGE PLANS		COMMENCE DRLG CSG TST & CMT	JOB	P8	kA	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06	pleted Operations (Cloed work) SEE RULE 1	early state all p	pertinent details	COMMENCE DRLG CSG TST & CMT OTHER , and give pertinent	JOB date, inclu	P8	ated	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of Starting any propose 01/27/06 - 02/06/06 MIRU to test well. For	pleted Operations (Cled work) SEE RULE 1	early state all page 103	pertinent details	COMMENCE DRLG CSG TST & CMT OTHER and give pertinent	JOB date, includes	ding estimates in the property of the property	ated	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Comparing any proposes 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in	pleted Operations (Class work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts	early state all page 103 nole, 1 ben + pkr, o/o	pertinent details t jt and jts v	COMMENCE DRLG CSG TST & CMT OTHER , and give pertinent ov/ corroded pin E. EOT @ 595	JOB date, includes. PU 4 7.20'. \	ding estimated in the property of the property	ated	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Comparing any proposed 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w.	pleted Operations (Class work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic	early state all page 103 nole, 1 ben + pkr, o/od not have	ertinent details t jt and jts v entry guide pkr, RIW w	COMMENCE DRLG CSG TST & CMT OTHER and give pertinent of the corroded pin be EOT @ 595 7/ 28 stands , la	JOB date, includes S. PU 4 7.20'. Note the content on the conte	ding estimated in the plant of	ated s I would n	kr.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Comparing any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW work RIH w/186 jts set RBP	pleted Operations (Clied work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts //tbg and pkr, dic @ 5955'. Load	early state all p 103 nole, 1 ben + pkr, o/o d not have and tst RE	t jt and jts v entry guide pkr, RIW w BP to 530#,	COMMENCE DRLG CSG TST & CMT OTHER And give pertinent of the corroded pin E. EOT @ 595 1/ 28 stands , la held OK. Load	date, incluing the second of t	ding estimated in the plant of	ated s I would n POW w/p s, held 0	kr.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load	pleted Operations (Cled work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulu	early state all p 103 nole, 1 ben + pkr, o/o d not have and tst RE us for integ	t jt and jts v entry guide pkr, RIW w BP to 530#,	COMMENCE DRLG CSG TST & CMT OTHER And give pertinent of the corroded pin E. EOT @ 595 1/ 28 stands , la held OK. Load	date, incluing the second of t	ding estimated in the plant of	ated s I would n POW w/p s, held 0	kr.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Comparing any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW work RIH w/186 jts set RBP	pleted Operations (Cled work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulu	early state all p 103 nole, 1 ben + pkr, o/o d not have and tst RE us for integ	t jt and jts v entry guide pkr, RIW w BP to 530#,	COMMENCE DRLG CSG TST & CMT OTHER And give pertinent of the corroded pin E. EOT @ 595 1/ 28 stands , la held OK. Load	date, incluing the second of t	ding estimated in the plant of	ated s I would n POW w/p s, held 0	kr.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load	pleted Operations (Cled work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulu	early state all p 103 nole, 1 ben + pkr, o/o d not have and tst RE us for integ	t jt and jts v entry guide pkr, RIW w BP to 530#,	COMMENCE DRLG CSG TST & CMT OTHER And give pertinent of the corroded pin E. EOT @ 595 1/ 28 stands , la held OK. Load	date, incluing the second of t	ding estimated in the plant of	ated s I would n POW w/p s, held 0	kr.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load	pleted Operations (Cled work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulu	early state all p 103 nole, 1 ben + pkr, o/o d not have and tst RE us for integ	t jt and jts v entry guide pkr, RIW w BP to 530#,	COMMENCE DRLG CSG TST & CMT OTHER And give pertinent of the corroded pin E. EOT @ 595 1/ 28 stands , la held OK. Load	date, incluing the second of t	ding estimated in the plant of	ated s I would n POW w/p s, held 0	kr.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load	pleted Operations (Cled work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulu	early state all p 103 nole, 1 ben + pkr, o/o d not have and tst RE us for integ	t jt and jts v entry guide pkr, RIW w BP to 530#,	COMMENCE DRLG CSG TST & CMT OTHER And give pertinent of the corroded pin E. EOT @ 595 1/ 28 stands , la held OK. Load	date, incluing the second of t	ding estimated in the plant of	ated s I would n POW w/p s, held 0	kr.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load	pleted Operations (Clark work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulued. Chart attach	early state all p 103 nole, 1 ben + pkr, o/o d not have and tst RE us for integ	t jt and jts v entry guide pkr, RIW w 3P to 530#, rity test. N	COMMENCE DRLG CSG TST & CMT OTHER And give pertinent of the corroded pin EDOT @ 595 28 stands , la held OK. Load MOCD did not	date, incluing the second of t	ding estimated in the plant of	ated s I would n POW w/p s, held 0	kr.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Comparing any proposed of 1/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load 420# for 30 min, charter	pleted Operations (Clark work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulued. Chart attach	early state all part of the period of the pe	t jt and jts v entry guide pkr, RIW w BP to 530#, rity test. N	COMMENCE DRLG CSG TST & CMT OTHER , and give pertinent of the corroded pin E. EOT @ 595 / 28 stands , la held OK. Load MOCD did not	s. PU 4 7.20'. \ tch onto and tst witness	ding estimated in the plant of	ated ated would n OW w/p s, held C est to	okr. OK
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compare date of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w.RIH w/186 jts set RBP RU hot oil truck to load 420# for 30 min, charter	pleted Operations (Classed work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulused. Chart attach	early state all p 103 nole, 1 ben + pkr, o/o d not have and tst RE us for integ	t jt and jts v entry guide pkr, RIW w BP to 530#, rity test. N	COMMENCE DRLG CSG TST & CMT OTHER And give pertinent of the corroded pin EDOT @ 595 28 stands , la held OK. Load MOCD did not	s. PU 4 7.20'. \ tch onto and tst witness	ding estimated in the plant of	ated s I would n POW w/p s, held 0	okr. OK
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Comparing any proposed of 1/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load 420# for 30 min, charter	pleted Operations (Clad work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulued. Chart attach	early state all part of the period of the pe	t jt and jts v entry guide pkr, RIW w BP to 530#, rity test. N	COMMENCE DRLG CSG TST & CMT OTHER , and give pertinent of the corroded pin E. EOT @ 595 / 28 stands , la held OK. Load MOCD did not	s. PU 4 7.20'. \ tch onto and tst witness	ding estimated in the plant of	ated ated would n OW w/p s, held C est to	okr. OK
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load 420# for 30 min, charter Thereby certify that the information at SIGNATURE TYPE OR PRINT NAME	pleted Operations (Classed work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulused. Chart attach	early state all part of the period of the pe	t jt and jts v entry guide pkr, RIW w BP to 530#, rity test. N	COMMENCE DRLG CSG TST & CMT OTHER , and give pertinent of the corroded pin E. EOT @ 595 / 28 stands , la held OK. Load MOCD did not	s. PU 4 7.20'. \ tch onto	ding estimated in the plant of	ated ated would n OW w/p s, held C est to	okr. OK
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load 420# for 30 min, charter Thereby certify that the information at SIGNATURE	pleted Operations (Clad work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulued. Chart attach	early state all part of the period of the pe	t jt and jts ventry guide pkr, RIW was pto 530#, rity test. Noweledge and	COMMENCE DRLG CSG TST & CMT OTHER , and give pertinent of COTTOOLE PIN E. EOT @ 595 // 28 stands , la held OK. Load MOCD did not belief.	JOB date, includes. PU 4 7.20'. Value onto and tst witness Support	ding estimate di	ated ated would n OW w/p s, held C est to	okr. OK
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load 420# for 30 min, charter Thereby certify that the information at SIGNATURE TYPE OR PRINT NAME (This space for State Use)	pleted Operations (Clad work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulued. Chart attach	early state all part of the pkr, o/o do not have and tst RE us for integrated.	t jt and jts ventry guide pkr, RIW was pto 530#, rity test. Noweledge and	COMMENCE DRLG CSG TST & CMT OTHER , and give pertinent of COTTOOLE PIN E. EOT @ 595 // 28 stands , la held OK. Load MOCD did not belief.	JOB date, includes. PU 4 7.20'. Value onto and tst witness Support	ding estimate di	ated ated would n OW w/p s, held C est to	okr. OK
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load 420# for 30 min, charter Thereby certify that the information at SIGNATURE	pleted Operations (Clad work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annulued. Chart attach	early state all part of the period of the pe	t jt and jts ventry guide pkr, RIW was pto 530#, rity test. Noweledge and	COMMENCE DRLG CSG TST & CMT OTHER , and give pertinent of the corroded pin E. EOT @ 595 / 28 stands , la held OK. Load MOCD did not	JOB date, includes. PU 4 7.20'. Value onto and tst witness Support	ding estimate di	ated would n OW w/p s, held C est to	okr. DK
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Compate of starting any propose 01/27/06 - 02/06/06 MIRU to test well. For IPC 2-3/8" tbg. Ran in hold pressure. POW w/RIH w/186 jts set RBP RU hot oil truck to load 420# for 30 min, charter Thereby certify that the information at SIGNATURE TYPE OR PRINT NAME (This space for State Use)	pleted Operations (Clared work) SEE RULE 1 und 1 jt tbg w/ h hole w/ 191 jts /tbg and pkr, dic @ 5955'. Load and test annuluded. Chart attach	early state all part of the pkr, o/o do not have and tst RE us for integrated.	t jt and jts ventry guide pkr, RIW was pto 530#, rity test. Noweledge and	COMMENCE DRLG CSG TST & CMT OTHER , and give pertinent of COTTOOLE PIN E. EOT @ 595 // 28 stands , la held OK. Load MOCD did not belief.	JOB date, includes. PU 4 7.20'. Value onto and tst witness Support	ding estimate di	ated would n OW w/p s, held C est to	okr. OK



-W3201101-