Submit 3 Copies To Appropriate District Office	State of New M Energy, Minerals and Natu		Form C-103 May 27, 2004	
District I 1625 N. French Dr., Hobbs, NM 87240	Energy, winerals and valural resources		WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-025-12504	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE 🗓 FEE 🗌	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Ga	as Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS I(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name o	r Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		North Hot	obs G/SA Unit	
1. Type of Well:		8. Well Number		
Oil Well X Gas Well Other		532		
2. Name of Operator			9. OGRID Number	
Occidental Permian Limited Partnership			157984	
3. Address of Operator			10. Pool name or Wildcat	
P.O. Box 4294, Houston, TX 77210-4294 4. Well Location			Hobbs: Grayburg - San Andres	
4. Well Location				
Unit Letter G :	2310 feet from the No	rth line and	1650 feet fr	om the <u>East</u> line
Section 32	Township 18-S	Range 38-E	NMPM	County Lea
	11. Elevation (Show whether		c.)	
3638 GL				
Pit or Below-grade Tank Application or Closure				
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness: mi	Below-Grade Tank: Volume	bbls; Construction	on Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	ING OPNS.	PLUG AND
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		ABANDONMENT
OTHER:		OTHER:		Г
13. Describe proposed or complet	ed operations. (Clearly state all pe	ertinent details, and giv	e pertinent dates, in	ncluding estimated date
of starting any proposed work or recompletion.). SEE RULE 1103. For Multipl	e Completions: Attach	wellbore diagram	of proposed completion
	See Attao		P. S.	SE RESTANCE SE
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan				
SIGNATURE Manu Stephen TITLE Regulatory Compliance Analyst DATE 7/19/06				
Type or print name Mark Steph	E-1 ens	mail address: Mark_	Stephens@oxy.com	M anhona No. (713), 366-5159

For State Use Only
APPROVED BY
Conditions of Approval, if any:

OC FIELD REPRESENTATIVE II/STAFF MANAGES 2 5 2006

Temporarily abandon well as per the following procedure:

- 1) MI \times RU. NU BOP and test well.
- 2) POOH with production equipment.
- 3) RIH with 5" CIBP and set at 3780'. Cap CIBP with 20' cement.
- 4) Pressure test casing and chart for the NMOCD.
- 5) ND BOP. RD \times MO \times clean location. Leave well with cap flange and pressure gauge.