

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

March 4, 2004

| | | |
|--|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | WELL API NO. 30-025-06925 |
| 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> | | 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 2. Name of Operator LANEXCO, INC., INC. | | 6. State Oil & Gas Lease No. |
| 3. Address of Operator 1105 WEST KANSAS, JAL, NM 88252 | | 7. Lease Name or Unit Agreement Name JOYCE PRUITT |
| 4. Well Location Unit Letter 0 : 660 feet from the SOUTH line and 1980 feet from the EAST line Section 31 Township 21S Range 37E NMPM County LEA | | 8. Well Number 2 |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) | | 9. OGRID Number 13046 |
| 10. Pool name or Wildcat EUMONT YATES 7 RIVERS QUEEN | | |
| Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached) | | |
| Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ; feet from the line and feet from the line | | |

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Smith & Marrs Casing Pullers is contracted to plug this well.

SEE CHANGES ON 2ND PAGE

*Plugging Procedure attached.

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Charles L. Mann TITLE Production Supt. DATE 8/1/06

Type or print name CHARLES MANN

E-mail address:

Telephone No. 505-395-3050

(This space for State use)

APPROVED BY Gary W. Wank

TITLE FIELD REPRESENTATIVE / STAFF MANAGER

Conditions of approval, if any

DATE

AUG 02 2006

Lanexco, Inc.
1105 West Kansas
Jal, New Mexico 88252
505/395-3056
Fax 505/395-3205

LANEXCO, INC.

PLUGGING PROCEDURE

JOYCE PRUITT #2
30-025-06925
EUMONT POOL
LEA COUNTY, NM

1. Move in and rig up plugging unit and equipment.
2. Pull existing production tubing and lay down.
3. Go in hole and tag existing plug at 3340'
4. Load hole with salt get.
5. Set 50 ft plug base of salt 2475/2525. — 2560'-2460' (100' PLUG OR 255X WHICH)
6. Set 50 ft plug top of salt 1225/1275. — 1300'-1200' EVER 15 GREATER
7. Set 25-sx plug 650/750. — W.D.C. + TAG
8. Set shoe plug 50/50 at 317 ft. — WOC + TAG
9. Surface plug — 10 sacks.
10. Set marker.

Joyce Pw: # No. 2

