

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-06922

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil / Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
CHEVRON USA INC

3. Address of Operator
15 SMITH ROAD, MIDLAND, TX 79705

4. Well Location
Unit Letter C : 660' Feet From The NORTH Line and 1980' Feet From The WEST Line
Section 31 Township 21-S Range 37-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT,GR, etc.)
3504' GL

7. Lease Name or Unit Agreement Name
H.T. MATTERN (NCT-B)

8. Well No.
10

9. Pool Name or Wildcat
PENROSE SKELLY; GRAYBURG

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: DEEPEN IN GRAYBURG ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-21-03: MIRU.
7-22-03: TAG PBTD @ 3786'. DRILL NEW FORMATION FR 3786-3821'.
7-23-03: TAG @ 3821'. DRILL NEW HOLE FR 3821-3886.
7-24-03: TAG @ 3885. DRILL NEW HOLE FR 3886-3970.
7-25-03: TAG TD @ 3970. NO FILL. TIH W/PKR & SET @ 3800. RU SWAB.
7-28-03: 10 HR SWAB TEST.
7-29-03: REL PKR @ 3800. TIH W/PKR & SET @ 3880. TIH W/PKR & SET @ 3800'. RU SWAB. 4 HR TEST.
7-30-03: RU SWAB. 5 HR TEST. REL PKR @ 3800. LOCATE PKR W/CCL. PERF 8 HOLES IN JT OF TBG BELOW INFL PKR. REL PKR @ 3880.
7-31-03: TIH W/BULL PLUGGED TBG & INFLATABLE PKR (USED AS RBP). SET PKR @ 3920. REL FROM ON/OFF TOOL. TIH W/INFLATABLE PKR & SET @ 3880. RU SWAB. 4 HR TEST. ACIDIZE GRAYBURG O.H. 3880-3920 W/1000 GALS 15% ANTI-SLUDGE HCL. SPOT ACID TO EOT. RU SWAB. 2 HR TEST.
8-01-03: RU SWAB. 8 HR TEST.
8-04-03: 2 HR SWAB TEST. REL INFLATABLE PKR. TIH W/RETR HEAD ON WS. FOUND PKR @ 3998. MOVED UP HOLE 33'. LATCH ONTO PKR. 5 HR SWAB TEST.
8-05-03: 4 HR SWAB TEST. REL INFLATABLE PKR @ 3887. TIH W/RBP & PKR. SET RBP # 4800. PKR @ 3652.
8-06-03: ACIDIZE PENROSE SKELLY PERFS 3736-94' W/3000 GALS 15% ANTI-SLUDGE HCL. 5 HR SWAB TEST ON PENROSE PERFS. REL TOOLS. TOH W/PKR & RBP.
8-07-03: RIG DOWN. TURN WELL OVER TO PRODUCTION TO HOOK UP FLOWLINE.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist

DATE 8/8/2003

TYPE OR PRINT NAME Denise Leake

Telephone No. 915-687-7375

(This space for State Use)

APPROVED Harry W. Wink TITLE FIELD REPRESENTATIVE II/STAFF MANAGER

CONDITIONS OF APPROVAL, IF ANY:

DATE

AUG 11 2003