State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-23206	
DISTRICT II			5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreen	nent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 20	
Type of Well: Oil Well			8. Well No. 131	
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323				
4. Well Location				
Unit Letter L : 1650	Feet From The South		t From The West	Line —
Section 20	Township 18-S	Range 38-E	, NMPM	Lea County
	11. Elevation (Show whether DF, RI 3662' DF	KB, RT GR, etc.)		
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS DELIGRA	ABANDONMENT
	<u></u>			ID/IIIDOIIIIEII
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	II JOB	
OTHER:		OTHER: Tempora	arily Abandon Well	X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. RUPU & RU.			1/3 ^{1/4}	-122
 ROPO & RU. Release packer, pull out of hole with packer & tubing. Set 5.5" CIBP @4000'. Dump bail 20' of cement on top of CIBP. Load casing and test to 600 PSI for 30 minutes and chart for the NMOCD. RDPU & RU. Clean location. Well is TA'd This Approval of Temporary 8/1/1/1 Abandonment Expires				
3. Set 5.5" CIBP @4000'. Dump bail 20' of cement on top of CIBP. 4. Load casing and test to 600 PSI for 30 minutes and chart for the NMOCD.				
5. RDPU & RU. Clean location.				
	This Approval of Temporal Abandonment Expires	norary 0/1///	23	Color William
Well is TA'd	This Approval of Terri	8/11/	- / C.	A CHOUNT
	Abandonment Expire.	,		, Or.
RUPU 08/10/06				
RDPU 08/11/06				10-075
				13. 12. 12. 13. 13. 13. 13. 13. 13. 13. 13. 13. 13
I hereby certify that the information above is constructed or	true and complete to the best of my know	ledge and belief. I further certify t	that any pit or below-grade tank h	ias been/will be
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	OCD-approved	
γ .		plan		
SIGNATURE WAS	-(d) agh man		Associate DATI	F 09/17/2004
	Denson E-mail address:	TITLE Administrative mendy johnson@oxy.com	TELEPHONE NO.	806-592-6280
For State Use Only OC FIELD REPRESENTATIVE II/STAFF MANAGER OC FIELD REPRESENTATIVE II/STAFF MANAGER				
APPROVED BY LOUY W. U	Jink	OC FIELD REPRE	SENTATIVE II/STAIT 76	re
CONDITIONS OF APPROVAL IF ANY:			-	AUG 2 1 2006
V				

