UNITEDSTATES

FORMAPPROVED

	DEPARTMENT OF THE INTERIO	781 11.171 11.17	Expires: March 31, 2007
	BUREAU OF LAND MANAGEMEN	5.	Lease Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS			C - 032096(b)
Do not use the abandoned w	nis form for proposals to drill o ell. Use Form 3160-3 (APD) for	r to re-enter an such proposals.	If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			. If Unit or CA/Agreement, Name and/or No
1. Type of Well Gas Well X Other			Well Name and No.
2. Nameof Operator Apache Corporation			ast Blinebry Drinkard Unit No. 18
3a. Address 3b. PhoneNo.(include area code) 6120 South Yale, Suite 1500 Tulsa OK 74136-4224 (918)491-5362			0. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Blinebry Oil & Gas (06660)
660' FNL & 330' FEL, Sec 11, T 21S, R 37E Unit A			ea County Jew Mexico
12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION	TYPEOF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice		Treat Reclamation nstruction Recomplete Abandon Temporarily Abandon	Well Integrity Other
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Pursuant to NMOCD Order No. F-12394			
1. MIRU. 2. Clean out well to PBTD. 3. Acidize Blinebry. 4. RIH with injection tubing and packer. 5. Notify NMOCD and BLM offices prior to pressure test casing per regulations. AUG 2 1 2006 6. Set up surface equipment. 7. Begin injection. LES BASYAK PETROLEMY S ACCUSED.			
14. I hereby certify that the foreg Name (Printed/Typed)	joing is true and correct		
Elaine Linton		Title Engineering Techni	ician
Signature Eller	ue Linton	Date 06/16/2006	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant heids legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title

Date