Form 3160-5

## INITEDSTATES

OCD-HOBBS

FORMAPPROVED

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT				OM B No. 1004-0137 Expires: March 31, 2007		
				5. Lease Se		
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an					LC - 032096(b) 6. If Indian, Allottee or Tribe Name	
abandoned w	ell. Use Form 3160 - 3	(APD) for such pro	oposals.			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No  8. Well Name and No.  East Blinebry Drinkard Unit No. 31  9. API Well No.  30-025-06541  10. Field and Pool, or Exploratory Area  Blinebry Oil & Gas (06660)  11. County or Parish, State  Lea County  New Mexico	
1. Type of Well GasWell X Other						
2. Name of Operator						
Apache Corporation						
3a. Address 3b. PhoneNo.(include area code)						
6120 South Yale, Suite 1500 Tulsa OK 74136-4224 (918)491-5362						
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						
330' FNL & 1980' FWL, Sec 12, T 21S, R 37E Unit C						
TYPE OF SUBMISSION		TYI	PEOF ACTION			
X Noticeof Intent	Acidize	Deepen	Production (Sta	rt/Resume)	Water Shut-Off	
Nonceof intent	AlterCasing	FractureTreat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Other	
Final Abandonment Notice			Temporarily Ab	andon		
I mai Abandonnient Notice	X Convert to Injection	PlugBack	Water Disposal			
13. Describe Proposed or Complete	ed Operation (clearly state all po	ertinent details, including es	timated starting date of	any proposed v	work and approximate duration thereof	
a are brokesar is to decheil mie	viousity of recomplete nonzon	LALLY, ELVE SUDSUITACE LOCATIO	ons and measured and tr	ne vertical der	one and rentment markers and renec	

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Pursuant to	NMOCD	Order No.	F-12394

- 1. MIRU.
- 2. Clean out well to PBTD.
- 3. Acidize Blinebry.
- 4. RIH with injection tubing and packer.
- 5. Notify NMOCD and BLM offices prior to pressure test casing per regulations
- 6. Set up surface equipment.
- 7. Begin injection.

LES BABYAK OLEUM ENGINEER

I hereby certify that the foregoing is true and correct Name (Printed/Typed) Elaine Linton Title Engineering Technician Date 06/16/2006 THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.