Submit 3 Copies To Appropriate District Office	Diate of 1	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 Revised March 25, 1999			
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Lifeigy, witherest that iterates iterated			WELL API NO.				
District II	OIL CONSERVATION DIVISION			30-025-27432				
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.			5. Indicate Type of Lease				
1000 Rio Brazos Rd., Aztec, NM 87410	Brazos Rd., Aztec, NM 87410 Santa Fe NIM 87505			STATE FEE 6. State Oil & Gas Lease No.				
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa 1 6, 14141 67505			L-6309				
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name:				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Central EK Qu	een Unit			
1. Type of Well:								
Oil Well ☐ Gas Well ☒ Other								
2. Name of Operator				8. Well No.				
Seely Oil Company				9. Pool name or Wildcat				
3. Address of Operator 815 W. 10 <sup>th</sup> St., Ft. Worth, TX 76102				EK Yates - Seven Rivers - Queen				
4. Well Location								
Unit Letter M	: <u>660</u> feet from the <u>\$</u>	3	line and 660	feet fr	om the W	line		
Section 9	Township 18S		inge 34E	NMPM	County I	Æ8		
10. Elevation (Show whether DR, RKB, RT, GR, etc.)								
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data								
NOTICE OF	SEQUENT RE							
PERFORM REMEDIAL WORK	☐ PLUG AND ABANDON		REMEDIAL WOR	K 🗆	ALTERING	CASING [		
TEMPORARILY ABANDON	☐ CHANGE PLANS		COMMENCE DR	ILLING OPNS.	PLUG AND ABANDON			
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST A	ND 🗆	, ibrii iboi i	1112111		
OTHER:			OTHER:					
12. Describe proposed or comple starting any proposed work). recompilation.	eted operations. (Clearly state . SEE RULE 1103. For Mult							
8/21/06 MIRU								
8/22/06 Tagged plug @ 4265 w								
8/23/06 RIH w/ tbg. tagged plu						To 2740. Pull		
up hole to 1703'. Spot 25 sx. cement plug to 1325'. Pull up hole to 444'. Circulate 30 sx cement to surface.  8/24/06 Cut off wellhead, Install dry hole marker. Clean location and rigged down equipment.								
Warren Cat our Weilineau, Illion	ii diy note marker. Cient ic	cation a	na riggea down e	quipment.				
					181			
Approved as to plugging of the Well Bore.  Liability under bond is retained until  surface restoration is completed.								
Liability under bond is retained until								
surface restoration is completed.								
				\ \ \				
				, , , , , , , , , , , , , , , , , , ,		- <i>5</i> 7		
					. files	<u>/</u>		
I hereby certify that the informat	•	e to the b	est of my knowledg	ge and belief.				
SIGNATURE Lands	Dendasa 1	ritle <u>C</u>	executive v	JP .	_ DATE <u></u> 8-	25-06		
Type or print name				Telen	hone No.			
(This space for State use)	^	The Will	ELD REPRESENTA					
٠	1, 2: 1/2		EID KELKESENTA	iive hystaff ma		AUG 2 8 200		
APPROVED BY Conditions of approval, if any:	y.wwk. 1	TITLE_			_ DATE			