

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06939
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	CENTRAL DRINKARD UNIT
8. Well No.	140
9. Pool Name or Wildcat	DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>H</u> : <u>2086'</u> Feet From The <u>NORTH</u> Line and <u>554'</u> Feet From The <u>EAST</u> Line Section <u>32</u> Township <u>21-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:


PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ CO2 SAND FRAC

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-24-06: MIRU RU. 7-25-06: TRIED TO REL TAC. TIH & FREE POINT TBG. TBG STUCK BELOW ANCHOR. CUT TBG BELOW ANCHOR @ 6405'. LD 2 3/8" TBG. 7-26-06: PU 297 JTS 2 7/8" WS. TAG FISH @ 6405'. LATCH ONTO FISH & JAR. FISH MOVED UP 6390'. MOVED TO 6387. 7-27-06: LOAD CSG W/40 BBLs. REL PSI & OPEN TIW VALVE. ESTAB CIRC. 7-28-06: TIH W/SHOE, WASH PIPE, BMPR SUB, JARS, TBG. GO OVER FISH. 7-31-06: TIH W/WASH PIPE & TAG @ 6533'. WASH OVER FISH TO 6563'. TIH W/OVERSHOT, JARS, & TBG. LATCH ONTO FISH. 08-01-06: TIH W/BIT & TAG @ 6524'. C/O TO 6605'. 8-02-06: RUN CCL/GR FR TD TO 5000'. TIH W/PKR & 3 1/2" FRAC TBG. 8-03-06: RAN TOTAL OF 203 JTS TBG. SET PKR @ 6459'. 8-04-06: PUMP 2000 GALS ACID & FLUSH W/60 BW. TIH W/SWAB. 8-07-06: SWABBING. 8-08-06: FRAC OPEN HOLE 6498-6605' W/492 BBLs WF145. FLOW WELL TO TANK. 8-09-06: OPEN WELL TO TANK. FLOW BACK ALL GAS. TIH W/SAND LINE. TAG SAND @ 5700. (EOT @ 6460). REL PKR. 8-10-06: W/O COIL UNIT. 8-11-06: TIH W/BIT & 1 1/2" COIL. TAG @ 5680. C/O TO 6450. 8-14-06: REL PKR. TIH W/BIT & TAG FILL @ 6474. PU ABOVE PERFS. 8-15-06: C/O FILL FR 6474-6518'. 8-16-06: TAG FILL @ 6518. D/O FR 6518-6538'. WASH DN THROUGH SAND TO 6550. D/O TO 6555'. 8-17-06: TAG FILL @ 6552. C/O FR 6552-6572'. TIH W/15 STANDS 2 7/8" WS FOR KILL STRING. 8-18-06: TIH W/BIT & TAG @ 6570'. D/O FILL FR 6570-PBTD @ 6606. 8-21-06: TIH W/PKR & SET @ 6441'. SWAB. 8-22-06: TIH W/PRISM LOG. SAND FR CSG SHOE TO TD. 8-23-06: TIH W/2 7/8" TBG. TEST TO 5000#. UNL; OAD & RACK PROD RODS. 8-24-06: TIH W/1.25 INSERT PUMP & RODS. LOAD TEST WELL. HANG WELL ON. RIG DOWN. FINAL REPORT



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist

DATE 8/28/2006

TYPE OR PRINT NAME

Denise Pinkerton

Telephone No. 432-687-7375

(This space for State Use)

APPROVED Harry W. Wink TITLE FIELD REPRESENTATIVE / STAFF MANAGER
CONDITIONS OF APPROVAL, IF ANY:

DATE

AUG 30 2006
DeSoto/Nichols 12-93 ver 1.0