Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-38063
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease  STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,	32447
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Boase Name of Sint rigitorite Name
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Seven Rivers Queen Unit
1. Type of Well: Oil Well	Gas Well Other Injection	8. Well Number 87
2. Name of Operator		9. OGRID Number
Arena Resources Inc.		220420
3. Address of Operator		10. Pool name or Wildcat
4920 S. Lewis, Suite 107, Tulsa, (	OK 74105	Seven Rivers Queen
4. Well Location		
Unit Letter M: 85 feet from the South line and 1232 feet from the West line		
Section 27	Township 22S Range 36E	NMPM Lea County
	11. Elevation (Show whether DR, RKB, RT, GR,	etc.)
Pit or Below-grade Tank Application	or Closure	
Pit type Depth to Grounds		Distance from nearest surface water
Pit Liner Thickness: mi	<del></del>	Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING		
TEMPORARILY ABANDON		DRILLING OPNS.□ P AND A 🛛
PULL OR ALTER CASING	MULTIPLE COMPL   CASING/CEM	ENT JOB
. 022 0117 (21211 0710110		
_		_
OTHER:	OTHER:	and sive notions data including a simple data
OTHER:  13. Describe proposed or com	pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date  Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or com		and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.	pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.	pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:  Approved as to plusting a second control of the con	Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level	Approved as to plugging of the Well B	Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level	Approved as to plugging of the Well B	Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:  Approved as to plusting a second control of the con	Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level	Approved as to plugging of the Well B	Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level	Approved as to plugging of the Well B	Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level	Approved as to plugging of the Well B	Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level  RD MO Rig  8/21/06  I hereby certify that the information	Approved as to plugging of the Well B Liability under bond is retained until surface restoration is completed.	Attach wellbore diagram of proposed completion  Ore.
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level  RD MO Rig  8/21/06  I hereby certify that the information	Approved as to plugging of the Well B	Attach wellbore diagram of proposed completion  Ore.
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level  RD MO Rig  8 / 2 / 6  I hereby certify that the information grade tank has been/will be constructed or	Approved as to plugging of the Well B Liability under bond is retained until surface restoration is completed.	Attach wellbore diagram of proposed completion  Ore.  edge and belief. I further certify that any pit or below- t  or an (attached) alternative OCD-approved plan
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level  RD MO Rig  8/21/06  I hereby certify that the information	Approved as to plugging of the Well B Liability under bond is retained until surface restoration is completed.	Attach wellbore diagram of proposed completion  Ore.  edge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level  RD MO Rig  8 / 2 / 6  I hereby certify that the information grade tank has been/will be constructed or	Approved as to plugging of the Well B Liability under bond is retained until surface restoration is completed.  Approved as to plugging of the Well B Liability under bond is retained until surface restoration is completed.	Attach wellbore diagram of proposed completion  Ore.  edge and belief. I further certify that any pit or below- t  or an (attached) alternative OCD-approved plan  .  rvisor DATE 8-28-06 .
OTHER:  13. Describe proposed or com of starting any proposed wor recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level  RD MO Rig  Signature  Signature  A	Approved as to plugging of the Well B Liability under bond is retained until surface restoration is completed.  Above is true and complete to the best of my knowled according to NMOCD guidelines , a general permit above is remained to the surface restoration.  TITLE Production Superal address:	Attach wellbore diagram of proposed completion  Ore.  edge and belief. I further certify that any pit or below- t  or an (attached) alternative OCD-approved plan .  rvisor DATE 8-28-06 .  Telephone No. (505) 738-1739
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level  RD MO Rig  Signature  Type or print name For State Use Only	Approved as to plugging of the Well B Liability under bond is retained until surface restoration is completed.  Approved as to plugging of the Well B Liability under bond is retained until surface restoration is completed.  TITLE Production Superal Palmer  E-mail address:  OC FIELD REPRESENTATIVE 11/3	Attach wellbore diagram of proposed completion  Ore.  edge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan or an (attached).  Telephone No. (505) 738-1739  STAFF MANAGER
OTHER:  13. Describe proposed or come of starting any proposed we or recompletion.  Set 100' plug from 850' to 750'.  Set 100' plug from 410' to 310'.  Set 60' plug at ground level  RD MO Rig  Signature  Signature  Type or print name  Danny M. F.	Approved as to plugging of the Well B Liability under bond is retained until surface restoration is completed.  Above is true and complete to the best of my knowled according to NMOCD guidelines , a general permit above is remained to the surface restoration.  TITLE Production Superal address:	Attach wellbore diagram of proposed completion  Ore.  edge and belief. I further certify that any pit or below- t  or an (attached) alternative OCD-approved plan .  rvisor DATE 8-28-06 .  Telephone No. (505) 738-1739