Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I			
P.O. Box 1980, Hobbs NM 88241-1980	OIL CONSERVATION 2040 Pacheco S		WELL API NO.
DISTRICT II	Santa Fe, NM 87505		30-025-20556
P.O. Drawer DD, Artesia, NM 88210	,	5	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6	5. State Oil & Gas Lease No. K-867
	ICES AND REPORTS ON WELL	22	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name MESA QUEEN UNIT
1. Type of Well: OIL GAS WELL WELL WELL	OTHER		
2. Name of Operator XERIC OIL & GAS CORPORATION			8. Well No. 17
3. Address of Operator P.O. BOX 352 MIDLAND TX 7970.	2	9). Pool name or Wildcat
4. Well Location Unit Letter M: 330	Feet From The SOUTH	Line and990	Feet From The WEST Line
Section 17	Township 16S Range		MPM LEA County
	10. Elevation (Show whether I	OF, RKB, RT, GR, etc.)	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS	EMEDIAL WORK OMMENCE DRILLING C ASING TEST AND CEM	
1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-1-1-12-1		THER:	
1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-12-1-1-1-1-12-1	peration (Clearly state all pertinent detail TAG @ 3160' & TAG @1150 S WOC & TAG @ 130		ates, including estimated date of starting any property of the starting and t
work) SEE RULE 1103. 7-29-03 SPOT 25 SKS 3400' WOC & SPOT 25 SKS @ 1300' WOC 7-30-03 PERF @ 600 SQUEEZE 50 SK	peration (Clearly state all pertinent detail TAG @ 3160' & TAG @1150 S WOC & TAG @ 130 ACE Approved as to Liability under		ates, including estimated date of starting any property of the starting and t
12. Describe Proposed or Completed Opwork) SEE RULE 1103. 7-29-03 SPOT 25 SKS 3400 WOC & SPOT 25 SKS 1300 WOC 7-30-03 PERF @ 600 SQUEEZE 50 SK SPOT 20 SKS 100 TO SURF. CIRCULATE MUD INSTALL P&A MARKER	peration (Clearly state all pertinent detail TAG @ 3160' & TAG @1150 S WOC & TAG @ 130 ACE Approved as to Liability under	plugging of the Webond is retained union is complete.	ates, including estimated date of starting any property of the starting and t
12. Describe Proposed or Completed Opwork) SEE RULE 1103. 7-29-03 SPOT 25 SKS 3400 WOC & SPOT 25 SKS 1300 WOC 7-30-03 PERF @ 600 SQUEEZE 50 SK SPOT 20 SKS 100 TO SURF. CIRCULATE MUD INSTALL P&A MARKER	peration (Clearly state all pertinent detail TAG @ 3160' & TAG @1150 S WOC & TAG @ 130 ACE Approved as to Liability under surface restorat	plugging of the Webond is retained union is complete.	ates, including estimated date of starting any property of the starting and t
12. Describe Proposed or Completed Opwork) SEE RULE 1103. 7-29-03 SPOT 25 SKS 3400' WOC & SPOT 25 SKS @ 1300' WOC 7-30-03 PERF @ 600 SQUEEZE 50 SK SPOT 20 SKS 100' TO SURF. CIRCULATE MUD INSTALL P&A MARKER	peration (Clearly state all pertinent detail TAG @ 3160' & TAG @1150 S WOC & TAG @ 130 ACE Approved as to Liability under surface restorat	plugging of the Webond is retained union is complete.	ates, including estimated date of starting any property of the starting and t

OC FIELD REPRESENTATIVE II/STAFF MANAGER